



**UNITED STATES  
NUCLEAR REGULATORY COMMISSION**

REGION III  
2443 WARRENVILLE ROAD, SUITE 210  
LISLE, IL 60532-4352

May 11, 2009

Mr. Charles G. Pardee  
Senior Vice President, Exelon Generation Company, LLC  
President and Chief Nuclear Officer (CNO), Exelon Nuclear  
4300 Winfield Road  
Warrenville IL 60555

SUBJECT: BYRON STATION, UNITS 1 AND 2 NRC COMPONENT DESIGN BASES  
INSPECTION (CDBI) INSPECTION REPORT 05000454/2009007(DRS);  
05000455/2009007(DRS)

Dear Mr. Pardee:

On March 27, 2009, the U.S. Nuclear Regulatory Commission (NRC) completed a component design bases inspection at your Byron Station, Units 1 and 2. The enclosed report documents the inspection results, which were discussed on March 27, 2009, with Mr. B. Adams and other members of your staff.

The inspection examined activities conducted under your license as they relate to safety and compliance with the Commission's rules and regulations and with the conditions of your license. The inspectors reviewed selected procedures and records, observed activities, and interviewed personnel.

Based on the results of this inspection, two NRC-identified findings of very low safety significance were identified. The findings involved violations of NRC requirements. However, because of their very low safety significance, and because the issues were entered into your corrective action program, the NRC is treating the issues as Non-Cited Violations in accordance with Section VI.A.1 of the NRC Enforcement Policy.

If you contest the subject or severity of these Non-Cited Violation, you should provide a response within 30 days of the date of this inspection report, with the basis for your denial, to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555-0001, with a copy to the Regional Administrator, U.S. Nuclear Regulatory Commission - Region III, 2443 Warrenville Road, Suite 210, Lisle, IL 60532-4352; the Director, Office of Enforcement, U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001; and the Resident Inspector Office at the Byron Station. In addition, if you disagree with the characterization of any finding in this report, you should provide a response within 30 days of the date of this inspection report, with the basis for your disagreement, to the Regional Administrator, Region III, and the NRC Resident Inspector at the Byron Station. The information you provide will be considered in accordance with Inspection Manual Chapter 0305.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter, its enclosure, and your response (if any), will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records System (PARS)

C. Pardee

-2-

component of NRC's Agencywide Documents Access and Management System (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Sincerely,

/RA/

Ann Marie Stone, Chief  
Engineering Branch 2  
Division of Reactor Safety

Docket Nos. 50-454; 50-455  
License Nos. NPF-37; NPF-66

Enclosure: Inspection Report 05000454/2009007 and 05000455/2009007  
(w/Attachment: Supplemental Information)

cc w/encl: Site Vice President - Byron Station  
Plant Manager - Byron Station  
Manager Regulatory Assurance - Byron Station  
Senior Vice President - Midwest Operations  
Senior Vice President - Operations Support  
Vice President - Licensing and Regulatory Affairs  
Director - Licensing and Regulatory Affairs  
Manager Licensing - Braidwood, Byron, and LaSalle  
Associate General Counsel  
Document Control Desk - Licensing  
Assistant Attorney General  
Illinois Emergency Management Agency  
J. Klinger, State Liaison Officer,  
Illinois Emergency Management Agency  
P. Schmidt, State Liaison Officer, State of Wisconsin  
Chairman, Illinois Commerce Commission  
B. Quigley, Byron Station

C. Pardee

-2-

component of NRC's Agencywide Documents Access and Management System (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Sincerely,

/RA/

Ann Marie Stone, Chief  
Engineering Branch 2  
Division of Reactor Safety

Docket Nos. 50-454; 50-455  
License Nos. NPF-37; NPF-66

Enclosure: Inspection Report 05000454/2009007 and 05000455/2009007  
(w/Attachment: Supplemental Information)

cc w/encl: Site Vice President - Byron Station  
Plant Manager - Byron Station  
Manager Regulatory Assurance - Byron Station  
Senior Vice President - Midwest Operations  
Senior Vice President - Operations Support  
Vice President - Licensing and Regulatory Affairs  
Director - Licensing and Regulatory Affairs  
Manager Licensing - Braidwood, Byron, and LaSalle  
Associate General Counsel  
Document Control Desk - Licensing  
Assistant Attorney General  
Illinois Emergency Management Agency  
J. Klinger, State Liaison Officer,  
Illinois Emergency Management Agency  
P. Schmidt, State Liaison Officer, State of Wisconsin  
Chairman, Illinois Commerce Commission  
B. Quigley, Byron Station

DOCUMENT NAME: G:\DRS\Work in Progress\Byron 2009-007 DRS ZXF.doc

Publicly Available       Non-Publicly Available       Sensitive       Non-Sensitive

To receive a copy of this document, indicate in the concurrence box "C" = Copy without attach/encl "E" = Copy with attach/encl "N" = No copy

OFFICE	RIII		RIII						
NAME	ZFalevits: Is		AMStone						
DATE	05/11/09		05/11/09						

**OFFICIAL RECORD COPY**

Letter to Mr. Charles Pardee from Ms. Ann Marie Stone dated May 11, 2009.

SUBJECT: BYRON STATION, UNITS 1 AND 2 NRC COMPONENT DESIGN BASES  
INSPECTION (CDBI) INSPECTION REPORT 05000454/2009007(DRS);  
05000455/2009007(DRS)

DISTRIBUTION:

Tamara Bloomer  
RidsNrrDorLp3-2 Resource  
RidsNrrPMByron Resource  
RidsNrrDirslrib Resource  
Patrick Hiland  
Kenneth OBrien  
Jared Heck  
Allan Barker  
Carole Ariano  
Linda Linn  
Cynthia Pederson  
DRPIII  
DRSIII  
Patricia Buckley  
Tammy Tomczak  
ROPreports Resource

U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Docket Nos: 50-454; 50-455

License Nos: NPF-37; NPF-66

Report No: 05000454/2009007; and 05000455/2009007(DRS)

Licensee: Exelon Generation Company, LLC

Facility: Byron Station, Units 1 and 2

Location: Byron, IL

Dates: February 23, 2009, through March 27, 2009

Inspectors: Z. Falevits, Senior Reactor Inspector, Lead  
A. Dunlop, Senior Reactor Inspector, Mechanical  
C. Brown, Senior Operations Inspector  
S. Lewis, Reactor Inspector, Electrical  
N. Della Greca, Electrical Contractor  
C. Baron, Mechanical Contractor

Observer: J. Gilliam, Reactor Engineer

Approved by: Ann Marie Stone, Chief  
Engineering Branch 2  
Division of Reactor Safety

Enclosure

## SUMMARY OF FINDINGS

IR 05000454/2009007(DRS), 05000455/2009007(DRS); 02/23/09 – 03/27/09; Byron Station, Units 1 and 2; Component Design Bases Inspection (CDBI).

The inspection was a 3-week onsite baseline inspection that focused on the design of components that are risk-significant and have low design margin. The inspection was conducted by regional engineering inspectors and two consultants. Two findings of very low safety significance were identified which were associated Non-Cited Violations (NCVs). The significance of most findings is indicated by their color (Green, White, Yellow, Red) using Inspection Manual Chapter (IMC) 0609, "Significance Determination Process (SDP)." Findings for which the SDP does not apply may be Green, or be assigned a severity level after NRC management review. The NRC's program for overseeing the safe operation of commercial nuclear power reactors is described in NUREG-1649, "Reactor Oversight Process," Revision 4, dated December 2006.

### A. NRC-Identified and Self-Revealed Findings

#### Cornerstone: Mitigating Systems

- Green. A finding of very low safety significance (Green) and associated NCV of 10 CFR Part 50, Appendix B, Criterion III, "Design Control," was identified by the inspectors for the failure to maintain the qualification bases for safety-related equipment. Specifically, the licensee failed to maintain/extend the qualified life of the Westinghouse molded case circuit breakers (MCCBs) after the manufacturer's qualifications ended at 20 years as required by 10 CFR Part 50, Appendix A and B. As a result, the licensee issued a condition report and performed an engineering evaluation, which supported continuing qualification of the MCCBs and an operability evaluation, which found the MCCBs operable.

The inspectors determined that the finding was more than minor because not maintaining qualified components in safety-related systems structures and components (SSCs) could lead to the inability to respond to design basis events. The finding screened as of very low safety significance because the finding was a design or qualification deficiency confirmed not to result in loss of operability or functionality. The inspectors identified a cross-cutting aspect associated with this finding in the area of problem identification and resolution because the licensee did not effectively incorporate pertinent manufacturer's operating experience into maintaining the qualification of the MCCBs. (P.2.(b)) (Section 1R21.3.b.(1))

- Green. A finding of very low safety significance (Green) and associated NCV of 10 CFR Part 50, Appendix B, Criterion XVI, "Corrective Actions," was identified by the inspectors for the failure to identify, and take corrective action to address adverse mold case circuit breaker (MCCBs) test results. Specifically, the licensee failed to recognize an excessive test failure rate, assess the impact on the installed MCCBs, promptly replace all failed MCCBs, and evaluate the past and current operability of the attached loads. As a result, the licensee issued a condition report and an operability evaluation, which found the MCCBs operable.

The inspectors determined that the finding was more than minor because not ensuring the function and operability of all required MCCBs supplying safety-related SSCs could lead to the inability to respond to design basis events. The finding screened as very low safety significance because it would not result in the total loss of a safety function. Specifically, the licensee evaluation showed that there was no loss of breaker coordination. The inspectors identified a cross-cutting aspect associated with this finding in the area of human performance, decision making because the licensee did not use conservative assumptions in decision-making. (H1.b)(Section 1R21.3.b.(2))

**B. Licensee-Identified Violations**

No violations of significance were identified.

## REPORT DETAILS

### 1. REACTOR SAFETY

#### **Cornerstone: Initiating Events, Mitigating Systems, and Barrier Integrity**

#### 1R21 Component Design Bases Inspection (71111.21)

##### .1 Introduction

The objective of the component design bases inspection is to verify that design bases have been correctly implemented for the selected risk significant components and that operating procedures and operator actions are consistent with design and licensing bases. As plants age, their design bases may be difficult to determine and an important design feature may be altered or disabled during a modification. The Probabilistic Risk Assessment (PRA) model assumes the capability of safety systems and components to perform their intended safety function successfully. This inspectible area verifies aspects of the Initiating Events, Mitigating Systems, and Barrier Integrity cornerstones for which there are no indicators to measure performance.

Specific documents reviewed during the inspection are listed in the Attachment to this report.

##### .2 Inspection Sample Selection Process

The inspectors selected risk significant components and operator actions for review using information contained in the licensee's PRA and the Byron Station, Standardized Plant Analysis Risk (SPAR) Model, Revision 3.21. In general, the selection was based upon the components and operator actions having a risk achievement worth of greater than 2.0 and/or a risk reduction worth greater than 1.005. The operator actions selected for review included actions taken by operators both inside and outside of the control room during postulated accident scenarios.

The inspectors performed a margin assessment and detailed review of the selected risk-significant components to verify that the design bases have been correctly implemented and maintained. This design margin assessment considered original design reductions caused by design modification, or power uprates, or reductions due to degraded material condition. Equipment reliability issues were also considered in the selection of components for detailed review. These included items such as performance test results, significant corrective action, repeated maintenance activities, maintenance rule (a)(1) status, components requiring an operability evaluation, NRC resident inspector input of problem areas/equipment, and system health reports. Consideration was also given to the uniqueness and complexity of the design, operating experience, and the available defense in depth margins. A summary of the reviews performed and the specific inspection findings identified are included in the following sections of the report.

This inspection constituted 27 samples as defined in Inspection Procedure 71111.21-05.

### .3 Component Design

#### a. Inspection Scope

The inspectors reviewed the Updated Safety Analysis Report (USAR), Technical Specifications (TS), design basis documents, drawings, calculations and other available design basis information, to determine the performance requirements of the selected components. The inspectors used applicable industry standards, such as the American Society of Mechanical Engineers (ASME) Code, Institute of Electrical and Electronics Engineers (IEEE) Standards and the National Electric Code, to evaluate acceptability of the systems' design. The NRC also evaluated licensee actions, if any, taken in response to NRC issued operating experience, such as Bulletins, Generic Letters (GLs), Regulatory Issue Summaries (RISs), and Information Notices (INs). The review was to verify that the selected components would function as designed when required and support proper operation of the associated systems. The attributes that were needed for a component to perform its required function included process medium, energy sources, control systems, operator actions, and heat removal. The attributes to verify that the component condition and tested capability was consistent with the design bases and was appropriate may include installed configuration, system operation, detailed design, system testing, equipment and environmental qualification, equipment protection, component inputs and outputs, operating experience, and component degradation.

For each of the components selected, the inspectors reviewed the maintenance history, system health reports, operating experience-related information and licensee corrective action program documents. Field walkdowns were conducted for all accessible components to assess material condition and to verify that the as-built condition was consistent with the design. Other attributes reviewed are included as part of the scope for each individual component.

The following 16 component design reviews constituted 16 inspection samples as defined in IP 71111.21.

- Motor Driven Auxiliary Feedwater (AFW) Pump (2AF01PA): The inspectors reviewed the following component attributes: (1) the design and licensing basis of the component as documented in design and licensing documentation; (2) the motor driven auxiliary feedwater pump to verify its capability of providing makeup water to the steam generators; (3) the pump design parameters for transferring the pump suction source; (4) the calculations, and operating procedures related to these functions; (5) the pump cooling, room cooling, recent pump test results, and component nameplate data; (6) the automatic and manual pump control logic; (7) the results of the load flow and voltage calculation to determine whether sufficient power was available to start the motor during worst case degraded voltage and service conditions; (8) the pump performance and brake horsepower requirement to determine whether the motor was adequately sized for the worse case load condition and whether this rating was adequately included in the diesel generator loading calculation; (9) the electrical and cable drawings to verify separation from other trains and divisions and to check for safety/non-safety interfaces; (10) corrective actions and trending data to assess potential component degradation; and (11) recent pump related preventative maintenance and corrective actions. In addition, the inspectors performed walkdowns of the auxiliary feedwater pump to verify the material condition of the components.

- Auxiliary Feedwater Pump Discharge Header to Steam Generators 2D Isolation Valve (2AF013H): The inspectors reviewed the following component attributes: (1) motor operated valve (MOV) calculations and analysis to ensure the valve was capable of functioning under design conditions which included calculations for required thrust, maximum differential pressure, and valve weak link analysis; (2) diagnostic and inservice testing (IST) results to verify acceptance criteria were met and performance degradation would be identified; (3) the electrical and cable drawings to verify separation from other trains and divisions; (4) the licensee's actions taken in response to vendor and generic communications; (5) power and control sources and control logic for this valve and; (6) voltage drop for both power and control circuits, overload and short circuit protection for the valve motor.
- Component Cooling (CC) Water Heat Exchanger Outlet Isolation Valve (2SX007): The inspectors reviewed the following component attributes: (1) MOV calculations and analysis to ensure the valve was capable of functioning under design conditions. This included calculations for required thrust, maximum differential pressure, and valve weak link analysis; (2) diagnostic testing results were reviewed to verify acceptance criteria were met and performance degradation would be identified; (3) the control logic and power and control sources for this valve; (4) the voltage drop for both power and control circuits; and (5) the overload and short circuit protection for the valve motor.
- 0B Diesel Driven Essential Service Water (ESW) Makeup Pump (0SX02PB): The inspectors reviewed the following component attributes: (1) the diesel driven essential service water makeup pump to verify its capability of providing water to the essential service water cooling tower basins under post-accident conditions; (2) the design basis of the component as documented in design and licensing documentation; (3) the pump design with regard to flow and head capacity, nameplate data, pump and diesel cooling, adequate submergence and net positive suction head (NPSH), and minimum flow capability; (4) the component licensing basis, calculations, and operating procedures related to these functions; (5) recent pump test results, pump strainer design, fuel system design, the combustion air supply, the exhaust system design, and component nameplate data; (6) the design of the diesel engine electrical starting system, batteries and charger; (7) recent preventative and corrective maintenance activities; (8) the trending data to assess potential component degradation; (9) licensee's actions in response to vendor and generic communications; and (10) the pump control logic and power sources. In addition, the inspectors performed walkdowns of the pump, diesel driver, and fuel oil system to verify the material condition of the components.
- 2A Pressure Operated Relief Valve (PORV) (2RY455A): The inspectors reviewed the following component attributes: (1) the air-operated valve (AOV) calculations and analysis to ensure the valve was capable of functioning under design conditions, including low temperature overpressure (LTOP) conditions. This included calculations for required thrust, maximum differential pressure, and valve weak link analysis; (2) accumulator sizing calculations, system air pressure leak tests, preoperational test results, and set point analysis and calibrations, including the upcoming set point change for the low accumulator pressure alarm to ensure sufficient air was available in the accumulators on a loss of instrument

air, the inspectors reviewed; (3) diagnostic and IST results to verify acceptance criteria were met and performance degradation would be identified; (4) the air-operated valve control logic and the control power source; and (5) the circuit protection and adequacy of voltage.

- 2A Pressurizer Relief Isolation Valve - Block Valve (MOV) (2RY8000A): The inspectors reviewed the following component attributes: (1) the MOV calculations and analysis to ensure the valve was capable of functioning under design conditions. This included calculations for required thrust, maximum differential pressure, pressure locking analysis, and valve weak link analysis; (2) diagnostic and IST results to verify acceptance criteria were met and performance degradation would be identified; and (3) the electrical and cable drawings to verify separation from other trains and divisions.
- 2A Safety Injection (SI) Pump (2SI01PA): The inspectors reviewed the following component attributes: (1) the SI system hydraulic calculations such as NPSH, vortexing, and pump deadheading to ensure that the pumps were capable of providing their accident mitigation function. This included verifying issues identified in the previous CDBI had been adequately addressed; (2) the capability to switchover the suction source to the discharge of the residual heat removal pumps; (3) the vendor specifications and pump curves to ensure that these parameters had been correctly translated into calculations, as required; (4) pump minimum flow requirements were assessed to ensure they were in accordance with vendor recommendations; (5) the design basis requirements to ensure that they were correctly translated into test acceptance criteria; (6) completed pump surveillances to ensure that actual performance was acceptable. This included the quarterly and comprehensive IST pump surveillances, along with the system flow balance tests; (7) the preventive and corrective maintenance history to determine whether any recent maintenance issues could adversely impact the functions of the pump; (8) the automatic and manual pump control logic and the results of the load flow and voltage calculation to determine whether sufficient power was available to start the motor during worst case degraded voltage and service conditions; and (9) the pump performance and brake horsepower requirement to determine whether the motor was adequately sized for the worse case load condition and whether this rating was adequately included in the diesel generator loading calculation.
- 2B Emergency Diesel Generator (EDG) (2DG01KB): The inspectors reviewed the following component attributes: (1) the emergency diesel generator design related to EDG room temperature, cooling system performance, and fuel availability and quality; (2) the Fuel Oil transfer pump circuitry to verify electrical separation; (3) the vendor manual, one-line diagram, equipment specification, and the vendor nameplate rating to determine the diesel generator rated output capability; (4) the breaker control logic and power source, diesel/generator start logic, minimum voltage available at breaker close and trip coils, protective relaying and fuse and breaker coordination; (5) the EDG loading study for the worse case design basis loading conditions; (6) the results of surveillance tests to verify that the diesel generator test conditions enveloped design basis and Technical Specification requirements; (7) the normal and off-normal operating procedures to determine whether appropriate load ratings and limitations were incorporated; (8) selected pumps and fans to determine that break horsepower

loads were determined and based on conservative design and operating conditions; and (9) the modification and corrective maintenance history to determine whether any recent modifications or maintenance issues could adversely impact diesel generator load capability. In addition, the inspectors performed walkdowns of the EDG to determine the material condition and the operating environment of the components.

- 4160Vac Essential Switchgear Bus 242 (2AP06E): The inspectors reviewed the following component attributes: (1) essential switchgear bus 242 and its capability to supply adequate voltage to the loads; (2) the automatic and manual transfer schemes and logic between alternate offsite sources and the emergency diesel generator; (3) the control power sources and available voltage to ensure that adequate voltage would be available for the breaker open and close coils and spring charging motors; (4) the breakers rating protective relays setting and calibration, available short circuit and capability of the breaker to interrupt fault currents; (5) the load flow conditions to determine whether the transformers had sufficient capacity to support their required loads under worst case accident loading conditions; (6) voltage drop calculations to verify that adequate voltage was available at buses and components at various voltage levels under worst loading and degraded voltage conditions; (7) the degraded voltage analysis and setting and calibration of undervoltage and degraded grid voltage relays, grid voltage profile during previous ten years and communication between grid and plant operators; (8) the maintenance history of breakers and selected corrective action reports; and (9) the related breakers preventive maintenance to determine whether any recent maintenance issues could adversely the functions of the pump. In addition, the inspectors conducted plant walkdowns to determine the material condition and the operating environment of the switchgear, breakers and protective relaying.
- Crosstie Capability of Switchgear Bus 242 (2AP06E) and 2B Emergency Diesel Generator (2DG01KB): The inspectors reviewed the following component attributes: (1) the crosstie capability of the 4160Vac essential bus and its sources to other plant essential buses and to the ESF Component Cooling (CC) switchgear bus; (2) the interlocks provided between the various supply and tie breakers, automatic and manual transfer schemes and logic adopted and the electrical separation and isolation at the CC switchgear; (3) the breaker control power sources and available voltage to ensure that adequate voltage would be available for the breaker open and close coils and spring charging motors; (4) Breakers rating and protective relays setting and calibration as well as the protective relay coordination between supply and tie breakers; and (5) maintenance history of breakers. In addition, the inspectors conducted plant walkdowns to determine the material condition and the operating environment of the CC switchgear and physical separation provided among incoming and outgoing cables.
- 480Vac MCC 232X-2 (2AP27E): The inspectors reviewed the following component attributes: (1) the 480 Vac essential motor control center (MCC) and its capability to supply adequate voltage to the loads; (2) the voltage drop calculation related to this bus to confirm that adequate voltage was available to the components supplied by the bus under worst loading and degraded voltage conditions; (3) the bus and breaker rating and the protection provided, including

short circuit calculations and breaker coordination; (4) the automatic and manual transfer schemes and logic between alternate offsite sources and the emergency diesel generator; and (5) selected corrective action reports. In addition, the inspectors conducted plant walkdowns to determine the material condition and the operating environment of the motor control center.

- 125Vdc Station Battery 212 (2DC02E): The inspectors reviewed the following component attributes: (1) electrical calculations for the 212 safety-related 125Vdc station battery. These included battery sizing and loading, room hydrogen generation, battery capacity for design basis events and a station blackout event, and the voltage drop calculations; (2) the inspectors verified the station's design capability to cross-connect to the opposite unit if necessary and that adequate voltage existed to allow for this design feature; (3) the battery surveillance tests and performance history including verification of cell voltage, charging, specific gravity, electrolyte level, and temperature corrections to ensure acceptance criteria were met and performance degradation would be identified; and (4) operating procedures associated with the battery and its associated chargers to ensure they were in accordance with vendor recommendations. In addition, the inspectors conducted a visual inspection of the batteries to assess the physical and material condition of the batteries and reviewed condition reports to verify identification of adverse conditions or trends.
- Battery Charger 212 (2DC04E): The inspectors reviewed the following component attributes: (1) the electrical calculations for the safety-related battery chargers including sizing and voltage drop calculations; (2) periodic testing and test data to ensure acceptance criteria were met and any degradation would be identified; (3) condition reports, and assessed the physical and material condition of the chargers; and (4) the maintenance program on the electrolytic capacitors to verify proper identification of adverse conditions or trends.
- 125Vdc Bus 212 (2DC06E): The inspectors reviewed the following component attributes: (1) the 125Vdc buses and panel breakers associated with battery 212 and fuse sizing to ensure that their short circuit interrupting capability was adequate for the available short circuit current; and (2) verified the minimum voltage required on the DC Bus will be available to carry the safety-related loads. In addition, the inspectors performed a visual inspection on observable portions of the 125Vdc distribution center to assess material condition.
- Fire Protection (FP) Pump (0FP03PB): The inspectors reviewed the following component attributes: (1) the diesel driven fire protection (FP) pump; (2) the design and licensing basis of the component as documented in design and licensing documentation; (3) the pump design with regard to flow and head capacity, nameplate data, pump and diesel cooling, adequate submergence and NPSH, and minimum flow capability; (4) the component licensing basis, calculations, and operating procedures related to these functions; (5) pump strainer design, fuel system design, the combustion air supply, the exhaust system design, and component nameplate data; (6) the design of the diesel engine electrical starting system, batteries and charger; (7) recent pump test results; and (8) recent preventative maintenance and corrective actions. In addition, the inspectors performed field walkdowns of the pump, diesel driver, and fuel oil system to verify the material condition of the components.

- Steam Generator PORV and Block Valves (1MS018A (Hydraulic) and 1MS019A (Manual)): The inspectors reviewed the following component attributes: (1) the steam generator power operated relief valve (SG PORV) and block valve design related to their function during a steam generator tube rupture (SGTR) event; (2) the design and licensing basis of the components as documented in design and licensing documentation; and (3) the valves design with regard to their capability to open and close as required by plant accident analyses. The review included valve calculations, test results, and post accident environmental conditions. In addition, the inspectors evaluated the potential single failure of valves and associated power supplies under accident conditions as well as the operator action times associated with opening and closing the valve.

b. Findings

(1) Failure to Maintain/Extend the Qualification Basis for Molded-Case Circuit Breakers (MCCBs) Used in Safety-Related Applications Greater than 20 Years

Introduction: A finding of very low safety significance and associated NCV of 10 CFR Part 50, Appendix B, Criterion III, "Design Control," was identified by the inspectors for the failure to maintain the qualification basis for safety-related and important-to-safety MCCBs greater than 20 years old.

Description: On February 25, 2009, the inspectors identified that the licensee failed to maintain/extend the qualification basis for the installed Westinghouse MCCBs that were greater than 20 years old. Specifically, Procedure LS-AA-115, "Operating Experience Procedure," Revision 13, Attachment 4, "OPEX [operating experience] Document List/Classification," requires a formal review of Westinghouse Technical Bulletins. Attachment 1, "OPEX Reviewer's Guidelines," provides detailed steps for reviewing any OPEX and recommending actions to appropriately incorporate the results of the review into applicable licensee processes.

Assignment report (AR) 534100, "West TB-06-2 MCCB Aging," dated September 21, 2006, Assignment 02 was initiated to perform a subject matter expert review of Westinghouse Technical Bulletin (TB) 06-2. In AR 534100, Assignment 02, approved on December 6, 2006, the reviewer responded "NO" to the Step 4 Question, "Does this OPEX have any impact on the Operability of structures, or components"? The reviewer answered "NO" to Step 10 of Attachment 1, "Are there other plant systems/applications affected by this OPEX document"? The licensee response to the Step 16 Question, "Does this OPEX document have any impact on design data in controlled databases"? was "Not at this time." The inspectors noted that the action plan in Step 26 did not address extending/maintaining the qualification of the Westinghouse MCCBs that were greater than 20 years old. Specifically, there was no documented response to the TB-06-2 conclusion, in part, "For safety-related applications, the qualification basis must be maintained and extended for the breakers over 20 years old."

Section 8.1.16, "Qualification of Class 1E Equipment for Nuclear Power Plants," of the Byron USFAR states, in part, that the licensee complies with the intent of IEEE 323-1974. The IEEE 323 defines *qualified life* as, "The period of time, prior to the start of a design basis event, for which equipment was demonstrated to meet the design requirements for the specified service conditions. NOTE – At the end of the qualified life, the equipment shall be capable of performing the safety function(s) required for the

postulated design basis and post-design basis events.” Paragraph 4) of Section 6.9, “Extension of Qualified Life,” of the IEEE 323, states, “Periodic Maintenance, testing, and replacement/refurbishment programs based on manufacturers’ recommendations and sound engineering practices may be used to extend the equipment’s qualified life, where justified.” Paragraph 6) states, “Qualified life may be extended if it can be shown through subsequently developed data that an age-conditioning procedure, which limited the life of Class 1E equipment, is in fact conservative. Designated as acceptable for extending qualified life, the subsequently developed data shall contain quantitative evidence justifying the extended qualified life.”

The TB-06-2 stated, “the qualified life/design life extension can be justified by using a combination of a preventive maintenance program and aging analysis based on the actual service conditions.” The statement in TB-06-2 was in agreement with the statements in IEEE 323.

Based on the above, the inspectors concluded that the reviewer had incorrectly answered the questions in AR 534100. Specifically, because the bulletin involved the qualifications of the MCCBs, it had an impact on operability, impacted multiple safety-related systems, and involved design data.

After questioning by the inspectors, the licensee generated Engineering Change (EC) 374545, “Documentation of Justification for Continued Use of Westinghouse Breakers for Greater Than 20 Years and of Out of Tolerance Breakers Following a Surveillance [test] Until The Breakers Are Replaced,” dated March 6, 2009. The inspectors reviewed EC 374545 and noted the evaluation focused on MCCBs that tested high above the acceptance tests value until a replacement MCCB could be scheduled. The licensee also determined the continued use of Westinghouse type HFB breakers that had been in service greater than 20 years to be acceptable based on the type/apparent cause of breaker out-of-tolerances; similar Braidwood experiences (same type and age of MCCBs), PM Program/testing procedures, maintained breaker coordination, maintained short-circuit and overload protection, and breaker performance monitoring. However, the inspectors noted that no subsequent developed data containing quantitative evidence justifying the extended qualified life was presented. Specifically, the licensee had started the MCCB test program in 2001 and did not have any second round results to compare to the first round.

After additional discussions, the licensee generated AR 898543, “Westinghouse TB 06-02 Review Issue – 2009 CDBI,” on March 27, 2009, to document the lack of quantitative evidence that the Byron MCCBs were performing better than the norm discussed in TB-06-2 and that the licensee had maintained/extended the Westinghouse type HFB MCCB qualified life past 20 years. The inspectors noted that licensee’s discussion centered on multiple samples of the MCCBs with similar test results over several outages as the basis for stating that a negative trend due to aging did not exist.

Analysis: The inspectors determined that the failure to maintain/extend the qualified life of the Westinghouse molded case circuit breakers (MCCBs) was a performance deficiency. The performance deficiency was determined to be more than minor in accordance with IMC 0612, “Power Reactor Inspection Reports,” Appendix B, “Issue Disposition Screening,” because the finding was associated with the Mitigating Systems cornerstone attribute of equipment performance and affected the cornerstone objective of ensuring the availability of multiple safety-related systems and components to

respond to initiating events to prevent undesirable consequences. Specifically, not maintaining qualified components in safety-related SSCs could lead to the inability to respond to design basis events.

The inspectors determined the finding could be evaluated using the SDP in accordance with IMC 0609, "Significance Determination Process," Attachment 0609.04, "Phase 1 - Initial Screening and Characterization of Findings," Table 4a for the Mitigating Systems cornerstone. The finding screened as of very low safety significance (Green) because the finding was a design or qualification deficiency confirmed not to result in loss of operability or functionality. Specifically, no actual loss of function could be attributed to operating with MCCBs greater than 20 years old and the licensee was able to justify maintaining/extending the qualified life based on no evidence that the MCCB test failure rate had increased. A licensee operability evaluation found the MCCBs to be operable.

This finding has a cross-cutting aspect in the area of problem identification and resolution because the licensee did not effectively incorporate pertinent manufacturer's operating experience into maintaining the qualification of the Westinghouse MCCBs. (P.2.b)

Enforcement: Title 10 CFR Part 50, Appendix B, Criterion III, "Design Control," requires in part, that measures shall be established for the selection and review for suitability of application of materials, parts, equipment, and processes that are essential to the safety-related functions of the structures, systems, and components.

Contrary to the above, from November 8, 2006 to March 27, 2009, the licensee failed to review the suitability of the components essential to the design basis specifications. Specifically, the licensee failed to maintain/extend the qualified life of the MCCBs after the manufacturer's qualifications ended at 20 years; as required by 10 CFR Part 50, Appendix A and B. Because this violation was of very low safety significance and it was entered into the licensee's corrective action program as CR-898543, this violation is being treated as an NCV, consistent with Section VI.A.1 of the NRC Enforcement Policy (NCV 05000454/455/2009007-01(DRS)).

## (2) Inadequate Analysis of Molded-Case Circuit Breaker Test Data

Introduction: The inspectors identified a finding of very low safety significance (Green) and associated NCV of 10 CFR Part 50, Appendix B, Criterion XVI, "Corrective Actions," in that the licensee had failed to properly evaluate the impact of molded-case circuit breaker (MCCB) problems identified during testing.

Description: In 2001, in response to MCCB failures noted in the industry, the licensee initiated a MCCB testing and preventive maintenance program for both units. The licensee identified a 1.26 percent failure rate for the last four outages; however, a breaker was only considered to have failed if it did not trip or if it failed to coordinate with the upstream feeder breaker (the licensee's maintenance rule failure criteria).

The inspectors reviewed the MCCB acceptance-test results from previous groups of MCCBs tested and noted the following results:

- In B1R14 (the Fall 2006 outage), 87 of 150 MCCBs tested passed, 59 breakers tripped out of tolerance (magnetic instantaneous trip), 2 failed to trip, 1 failed to reset, 1 failed the thermal trip test for a 42 percent failure rate;
- In B2R13 (Spring 2007), 18 of 94 breakers tested failed, a 19 percent failure rate;
- In B1R15 (Spring 2008) 30 of 113 MCCBs tested failed, a 26.5 percent failure rate; and
- In B2R14 (Fall 2008) 21 of 119 MCCBs tested failed, a 17.6 percent failure rate.

Of total population of 569 safety-related MCCBs, the inspectors noted that 476 (277 fixed magnetic and 199 adjustable magnetic) had been tested during the four outages. Out of the 199 adjustable magnetic MCCBs, 128 failed the test (121 out-of-tolerance, 7 failed to trip or failed to reset), a 64.3 percent failure rate. There was a 1.8 percent failure rate (5 of 277) in the fixed magnetic MCCBs.

The inspectors noted that the actual acceptance test failure rate for either of the adjustable or fixed magnetic trip MCCBs was higher than the licensee's noted failure rate of 1.26 percent. The licensee viewed the out-of-tolerance high test result as acceptable conditions for operability and therefore, did not include these in the failure rate. The inspectors identified the following concerns:

- Procedure MA-AP-723-450, "Molded Case Circuit Breaker ODEN Testing," Revision 0, Step 3.2.8 stated, "A breaker failure is when a breaker **does not trip within its trip range** [emphasis added] or does not provide breaker coordination. The inspectors noted that the licensee's failure rate did not include those breakers which did not trip within the trip range.

In response to the inspectors' questions, the licensee stated that the breaker performance was monitored based on population sampling of breaker types. Specifically, a population of a breaker type was tested at every outage and the collective results would be used to determine acceptability of the remaining population not tested. In only recognizing a 1.26 percent failure rate, the licensee did not identify the negative performance trend therefore, did not adequately assess the acceptability of the total population or did not initiate appropriate action to plan and accomplish corrective actions in a timely manner. The inspectors also noted that the licensee had not taken any actions to address an initial 42 percent breaker failure rate and similar results from subsequent outage testing.

- The licensee did not immediately replace installed MCCBs that failed to trip within the trip range. The licensee initiated an operability determination to justify continued operation until such time that it could be replaced. The inspectors were informed that the licensee considered the risk of replacing the failed breaker immediately and performing the required post-maintenance tests (PMTs) to be greater than the risk of leaving breakers that tripped out-of-tolerance high in service. When the inspectors pointed out that, as a requirement for testing, the electrical panel was de-energized and ideal for MCCB replacement and the PMTs, the licensee agreed that there would be no additional risk for the individual task. However, the licensee was concerned that the unplanned work could lead to human performance and coordination issues incurred by changing outage plans and scope.

- The inspectors reviewed five condition reports (CRs) generated for MCCBs, which failed to trip within range. For four of the five CRs, the licensee concluded the MCCBs were operable because breaker coordination was maintained and the feed to the load was not impacted. This was for trip acceptance values from 11.2A to 34A. The fifth CR (827831) was for a 3A MCCB and the coordination was again the subject of the comments. The licensee noted that the 10A test value for this breaker was less than 3741A (the test value for the largest MCCB on the MCC) and that the largest MCCB coordinated with the feeder breaker; therefore, the [failed] 3A breaker was operable in this condition. The inspectors noted that the operability determinations did not address the design operability of the load with the failed MCCB where the wire ampacity is normally 125 percent of the expected full load current and the breaker is less than or equal to the wire ampacity. The inspectors concluded that shift management did not have sufficient information to make an informed operability decision.
- In CR 897630, "CDBI – Byron Inspection Testing Issues," dated March 25, 2009, the licensee stated that breakers left in place would be replaced during the next work window or outage. However, when asked if any failed MCCBs were still installed in the plant, the licensee identified seven safety-related MCCBs that had not been replaced; two from the last (October 2008) outage, four from the September 2006 outage, and one from the April 2007 outage. The inspectors noted that with the exception of the two MCCBs identified during the October 2008 outage, the remaining MCCBs should have been replaced in accordance with the licensee's procedures and that the operability of these breakers should have been reassessed when the licensee failed to or decided not to replace the MCCBs.

While investigating Assignment 03 to CR 897630, the licensee found eight additional safety-related MCCBs that had failed testing in September 2003 and had neither a CR nor a WR generated to address the condition; therefore, no operability determination had been made between the test failure and the time of discovery. The licensee noted this condition in CR 907731, "OOT Safety-Related HFB Breakers Installed Since September 2003," dated April 15, 2009. The licensee concluded the MCCBs were operable based on previous evaluations and coordination determination.

The inspectors determined that the licensee did not appropriately address failures of MCCBs to trip within the expected trip range. Specifically, MCCB test results indicated an excessive failure rate on adjustable-magnetic trip MCCBs; the operability determinations were narrowly focused (mainly on coordination only); the licensee had not promptly assess the impact on other safety-related, important-to-safety, and fire protection MCCB populations; the operations shift management did not have adequate information to assess operability of MCCBs; and the licensee had not replaced MCCBs which failed testing in a timely manner.

Analysis: The inspectors determined that the licensee's failure to properly evaluate adverse MCCB test results was a performance deficiency. Specifically, the licensee failed to have an adequate program to ensure the continued functionality and operability of the installed MCCBs that fall under the test program. The performance deficiency was determined to be more than minor in accordance with IMC 0612, "Power Reactor Inspection Reports," Appendix B, "Issue Disposition Screening," because the finding was associated with the Mitigating Systems cornerstone attribute of equipment performance and affected the cornerstone objective of ensuring the availability of

multiple safety-related systems and components to respond to initiating events to prevent undesirable consequences. Specifically, not ensuring the function and operability of all required MCCBs supplying safety-related SSCs could lead to the inability to respond to design basis events.

The inspectors determined the finding could be evaluated using the SDP in accordance with IMC 0609, "Significance Determination Process," Attachment 0609.04, "Phase 1 - Initial Screening and Characterization of Findings," Table 4a for the Mitigating Systems cornerstone. The finding screened as of very low safety significance (Green) because the finding would not result in the total loss of a safety function. Specifically, the licensee evaluation showed that there was no loss of breaker to supply breaker coordination.

This finding has a cross-cutting aspect in the area of human performance because the licensee did not use conservative assumptions in decision making and did not adopt a requirement to demonstrate that a proposed action is safe in order to proceed rather than a requirement to demonstrate that it is unsafe. Specifically, the decision to define a MCCB failure using a maintenance rule focused definition instead of the definition found in MA-AP-723-450 resulted in a significantly lower failure rate. As a result, the licensee did not identify the negative performance trend and therefore, did not adequately assess the acceptability of the total population. (H.1.(b)).

Enforcement: Title 10 CFR Part 50, Appendix B, Criterion XVI, "Corrective Action," requires, in part, that conditions adverse to quality are promptly identified and corrected. Contrary to the above, in September 2003, eight safety-related MCCBs failed acceptance tests (a condition adverse to quality); however, the licensee failed to promptly identify and correct this condition. Specifically, the licensee did not initiate a work request, a condition report, or an operability evaluation until April 2009. Because this violation was of very low safety significance and it was entered into the licensee's corrective action program as CR 907731, this violation is being treated as an NCV, consistent with Section VI.A.1 of the NRC Enforcement Policy (NCV 05000454/455/2009007-02(DRS)).

(3) Concerns with Licensee's Margin to Overfill (MTO) Analysis Related to Steam Generator Tube Rupture (SGTR) Event.

Introduction: The inspectors identified an unresolved item (URI) related to the licensee's evaluation of potential failures of the steam generator power operated relief valves (SG PORVs) during a postulated steam generator tube rupture (SGTR) event. Specifically, the licensee's margin to overfill (MTO) analysis was based on the failure of a single SG PORV to open and did not consider the potential failure of two valves to open due to a common electrical system failure (most limiting single failure).

Description: The inspectors reviewed the function on the SG PORVs during a postulated SGTR event. After a SGTR the operators open the SG PORVs associated with the intact steam generators to cooldown and depressurize the reactor coolant system. This operation would be time critical to prevent overfilling the ruptured steam generator and allowing liquid to enter the steam piping. The licensee's SGTR accident analysis was based on the single failure of one SG PORV to open when required; this was consistent with UFSAR Section 15.6.3 and Table 15.0-15. Failure of one SG PORV would enable operators to cooldown the reactor coolant system using the remaining two

SG PORVs. However, these electric/hydraulic valves require 480V power to operate. The four SG PORVs (MS018A-D) are powered from two redundant 480V electrical busses. Each bus provides power to two SG PORVs. Therefore, the failure of a single electrical power supply could result in the failure of two SG PORVs to operate. The inspectors questioned if the single failure assumptions used in the SGTR MTO analysis were in accordance with the Byron licensing basis. In response to this concern, the licensee stated that this question had been previously addressed in detail and provided several corrective action documents that addressed the function of the SG PORVs during a SGTR event.

The inspectors reviewed the following related corrective action documents:

- Issued Report (IR) 00680419 (initiated October 5, 2007), addressed local operator actions to open the SG PORVs after a SGTR. This IR questioned if the operators would be able to manually open the PORVs in the times assumed by the accident analysis. This IR identified that the single failure of one 480V bus would be more limiting than the loss of the entire 4kV electrical bus because all the ECCS pumps would continue to operate if only one 480V bus was lost. The loss of one 480V bus could result in the failure of two SG PORVs to open. The AR referred to a similar issue at Catawba Station, identified in 1997, which resulted in a LER.
- IR 00687783 (initiated October 22, 2007), addressed similar concerns to IR 00680419. A detailed licensing basis evaluation was performed to address these concerns in IR 00687783. This IR included an evaluation of the Byron current licensing basis (CLB) regarding postulated single failures. The IR evaluation stated, in part, "The conclusion drawn from the review is that for the design basis SGTR event, when the phrase single failure is used, its meaning is restricted to only single active failures and is not intended to convey all types of potential failures (i.e., passive and active)."
- IR 00706293 (initiated December 2, 2007), addressed various SGTR issues, including the MTO single failure concerns that were previously addressed by IR 00680419 and IR 00687783. Action AR 00706293-05 was initiated to perform a third party review of the SGTR single failure criteria. The independent review was completed on December 17, 2007. This review addressed the issue of passive versus active single failure, including an extensive review of regulatory requirements. The report stated, in part, "With regard to the semantics of 'single failure' vs. 'active single failure', there was nothing in the licensing history reviewed that specifically said passive failures do not need to be considered."
- Action AR 00713904 (initiated December 19, 2007), addressed the specific recommendations of the independent review report. The conclusions of this internal review did not agree with those of the independent reviewer (AR 00706293-05). The AR 00713904 re-review concluded that a passive single failure of electrical components did not need to be considered for the SGTR MTO accident analysis. This review addresses the apparent contradiction between the GDC and Chapter 15 of the SRP. Action AR 00713904-04 stated, in part, "The SRP on accident analyses and the GDC were prepared for different purposes. The GDC set forth a conservative set of rules for design that are intended to achieve defense in depth. The performance objectives of the GDC are high-level goals relating to the health and safety of the public. The SRP on accident analysis

provides specific direction regarding the methodology, assumptions, and acceptance criteria for detailed analysis of accidents and Anticipated Operational Occurrences (AOOs). For some accidents, the SRP may establish additional intermediate-level acceptance criteria at a lower level than the high level performance objectives of the GDC. It may be possible for a plant design to meet the high level performance objectives of the GDC for a broad spectrum of initiating events and failures (including multiple failures); but the ability to meet specific acceptance criteria in accident analysis may be contingent on the specific assumptions made (the SRP acceptance criteria was established with a specific set of assumptions in mind.)”

The review then addressed the question of why it was acceptable not to analyze for passive failures. The response to that question stated, “The underlying technical basis for the SRP’s approach to accident analysis is based on risk assessment methodology. Condition IV and other accident events have a very low frequency of occurrence. When combined with an additional random single active failure, the probability of the event combination is even lower (e.g., Condition IV events with two random active failures) would not add significant value in improving safety, and therefore is not required. A similar argument can be made for the combination of accidents with random passive failures.”

Finally, the review included a risk-based argument, which addressed how the above discussion related to the licensing of the SGTR accident analysis. This portion on the review includes a discussion of compliance with GDC 17, which states that the electrical system design meets the GDC 17 criteria but also includes the statement, “GDC 17 does not address the intermediate-level acceptance criteria for the SGTR accident analysis of preventing overfill of the ruptured SG. For the SGTR the high-level performance objective of the GDC is met, with or without SG overfill; and, therefore, one need not distinguish between active and passive failures.”

The inspectors noted that the Byron licensing basis for SGTR events was based on the generic Westinghouse analysis. The Westinghouse SGTR analysis (WCAP-10698) was based on a three-loop reference plant and the failure of a single SG PORV to open but did not specifically address electrical bus failures. In the single failure evaluation section, the WCAP stated, “common mode failures of all steam generator PORVs were not evaluated since electrical power and air supplies to the PORVs are largely plant specific...” The associated NRC evaluation (dated March 30, 1987), concluded that the WCAP analysis methodology was conservative, but pointed out that there may be major design differences between plants and required plant specific information. Section D.5 of the NRC evaluation required the following plant specific information, “A survey of plant primary and ‘balance-of-plant’ systems design to determine the compatibility with the bounding plant analysis in WCAP-10698. Major design differences should be noted. The worst single failure should be identified if different from the WCAP-10698 analysis and the effect of the difference on the margin of overfill should be provided.”

In response to the NRC, the licensee provided the required plant specific information (Commonwealth Edison letter, dated April 25, 1990). This letter included revision 1 of the SGTR analysis for the Byron and Braidwood plants. The analysis stated, in part, “The compatibility of the Byron/Braidwood systems with the WCAP-10698-P-A bounding plant analysis has been evaluated and no major design differences affecting the MTO

exist. The same limiting single failures as identified in WCAP-10698-P-A and Supplement 1 of WCAP-10698-P-A were utilized in the analysis...”

The NRC’s evaluation of the Byron/Braidwood plant specific SGTR analysis (NRC letter dated April 23, 1992) included a statement that the licensee had responded satisfactorily to this confirmatory issue.

Based on review of these corrective action documents, review of available Byron licensing documentation, and extensive discussions with Byron personnel, the inspectors were concerned that the licensee did not correctly evaluate the potential failure of the steam generator power operated relief valves (SG PORVs) during a postulated steam generator tube rupture (SGTR) event. The application of the single failure criteria is addressed in 10 CFR 50, Appendix A, the definition of “single failure” states:

“A single failure means an occurrence which results in the loss of capability of a component to perform its intended safety functions. Multiple failures resulting from a single occurrence are considered to be a single failure. Fluid and electric systems are considered to be designed against an assumed single failure if neither: (1) a single failure of any active component (assuming passive components function properly); nor (2) a single failure of a passive component (assuming active components function properly), results in a loss of the capability of the system to perform its safety functions.<sup>2</sup>

<sup>2</sup> Single failures of passive components in electric systems should be assumed in designing against a single failure. The conditions under which a single failure of a passive component in a fluid system should be considered in designing the system against a single failure are under development.”

This definition of “single failure” clearly states that single failures of passive components in electric systems should be assumed in designing against a single component failure. Based on this, it did not appear valid to make a distinction between active and passive failures of electrical components in accident analyses.

In addition, 10 CFR 50, Appendix A, GDC 17, states, in part:

- “An onsite electric power system and an offsite electric power system shall be provided to permit functioning of structures, systems, and components important to safety. The safety function for each system (assuming the other system is not functioning) shall be to provide sufficient capacity and capability to assure that: (1) specified acceptable fuel design limits and design conditions of the reactor coolant pressure boundary are not exceeded as a result of anticipated operational occurrences; and (2) the core is cooled and containment integrity and other vital functions are maintained in the event of postulated accidents.

The onsite electric power supplies, including the batteries, and the onsite electric distribution system, shall have sufficient independence, redundancy, and testability to perform their safety functions assuming a single failure...”

The inspectors were concerned that the licensee’s position that GDC 17 does not address the “intermediate-level acceptance criteria for the SGTR accident analysis of

preventing overfill of the ruptured SG” was not correct. The GDC 17 stated that onsite electric power supplies shall have sufficient independence, redundancy, and testability to perform their safety functions assuming a single failure. In accordance with the Byron licensing basis, preventing overfill of the ruptured steam generator was a safety function of the onsite electric power supply. Because the operator response time would not be adequate to locally open the SG PORVs after a SGTR event, the onsite electric power supply must be capable of performing that safety function, assuming a single failure (either active or passive).

The licensee initiated IR 00897354 on March 25, 2009, to document the NRC’s position on this issue; this IR stated that some mitigating actions would be initiated and stated that a new IR would be written upon formal receipt of NRC’s position. The IR 00897354 did not include corrective actions to address the licensee’s single failure assumptions.

The licensee also referred the inspectors to guidance included in NRC NUREG/CR 4893, dated May 1991. The inspectors reviewed the NUREG and noted that it discussed the assumption of worst single active failures in the analysis of SGTR events. However, the NUREG did not specifically address electrical failures and it was not clear if the reference to single active failures was applicable to electrical failures or just to fluid system failures.

In addition, the inspectors reviewed the applicability of unresolved item (URI) 05000454/2005002-06; 05000455/2005002-06 to this issue. As documented in NRC Inspection Report 05000454/2008008; 05000455/2008008 (dated May 5, 2008), the NRC determined that Byron was required to consider the passive failure of electrical components in the power supplies to essential service water cooling tower fans. This determination was based, in part, on the requirements of 10 CFR 50, Appendix A. The NRC determined that the provisions of 10 CFR 50.109(a)(4) were applicable, in that, a modification was necessary to bring the facility into compliance with the rules and orders of the Commission. The inspectors were concerned that this licensing basis issue was very similar to the SGTR MTO analysis issue, and that Byron failed to adequately evaluate the impact of this determination on the SGTR MTO analysis.

The inspectors have discussed this design and licensing basis issue with NRC staff in the Office of Nuclear Reactor Regulation. Due to complexity of establishing the appropriate design and licensing bases for this issue, this item is considered unresolved pending further NRC review (URI 05000454/455/2009007-03(DRS)).

(4) Insufficient Design Bases for Second-Level (Degraded) Voltage Timer Settings.

Introduction: The inspectors identified an unresolved issue (URI) related to licensee’s failure to develop adequate design bases for the second level (degraded) voltage timer settings. Specifically, the licensee failed to evaluate the impact of operating and/or starting safety-related equipment at a voltage as low as 75 percent of the 4.16 kV nominal bus voltage for as long as 5 minutes and 40 seconds during an event involving a degraded grid voltage condition without a loss of coolant accident (LOCA) signal.

Description: The inspectors determined that the licensee did not have an analysis to demonstrate the ability of the safety-related loads to mitigate an event involving a degraded grid voltage condition when a LOCA signal was not present. Specifically, the inspectors found that, during a degraded grid voltage condition, if a LOCA signal was

also present, after approximately ten seconds, the emergency diesel generators would start and accept the safety-related loads according to the prescribed load sequencing. However, if a LOCA signal was not present, the inspectors found that, after the ten-second delay, the degraded voltage condition resulted in an alarm in the control room and the start of a five-minute timer.

The inspectors noted that Section A.4 of IEEE 741-1997, "Degraded Voltage Relay Time Delay Settings," states, in part, that: "After the voltage setpoint for the degraded voltage relays has been established, additional analysis is required to determine the appropriate time delays. These analyses will involve investigation of transient conditions, such as block motor starting and the effect of increased load currents from degraded voltage operation, on both protective device operation and equipment thermal damage. Two time delays should be determined by: a) the first time delay should be of a duration that establishes the existence of a sustained degraded voltage condition (i.e., longer than a motor starting transient). Following this delay, an alarm in the control room should alert the operator to the degraded condition; and b) the second time delay should be of a limited duration such that the permanently connected Class 1E loads will not be damaged or become unavailable due to protective device actuation... Protective devices (i.e., circuit breakers, control fuses, etc.) for connected Class 1E loads should be evaluated to ensure that spurious tripping will not occur during this time delay period. Consideration should also be given for restarting/reaccelerating the loads, should transfer to the alternate or standby power source be required."

Similarly, NUREG 0800, Branch Technical Position (BTP) 8-6 states: "In addition to the undervoltage scheme provided to detect LOOP [loss of offsite power] at the Class 1E buses, a second level of undervoltage protection with time delay should be provided to protect the Class 1E equipment. This second level of undervoltage protection should satisfy the following criteria: a) The selection of undervoltage and time delay setpoints should be determined from an analysis of the voltage requirements of the Class 1E loads at all onsite system distribution levels and b) Two separate time delays should be selected for the second level of undervoltage protection based on the following conditions: i The first time delay should be long enough to establish the existence of a sustained degraded voltage condition (i.e., something longer than a motor-starting transient). Following this delay, an alarm in the control room should alert the operator to the degraded condition... ii. The second time delay should be limited to prevent damage to the permanently connected Class 1E loads... The bases and justification for such an action must be provided in support of the actual delay chosen."

Functionally, the Byron degraded voltage protection was consistent with the recommendations of IEEE-741 and BTP 8-6 in that the design included two levels of undervoltage protection and two separate time delays for the degraded voltage condition. However, the inspectors noted that, while the licensee had developed an adequate justification for the setting of the undervoltage relays and the first time delay, the licensee had not developed a technical justification for the second time delay.

The need for a full evaluation of degraded voltage conditions was originally identified by the NRC in 1976 and 1979 as a result of events at Millstone and Arkansas Nuclear One. These events and subsequent similar events were discussed in various NRC generic communication vehicles, including NUREG-0900-5 and Information Notices (INs) 79-04, 89-83, and more recently, IN 2000-06. In IN 89-83 the NRC described specific concerns with degraded voltage conditions and stated that, in the Millstone event, a grid voltage

drop combined with voltage drops produced by the step-down transformers “reduced the control power voltage within individual motor control centers and individual 480 Volt controllers to a level that was insufficient to actuate the main line controller contactors. As a result, when the motors were signaled to start, the contactor control power fuses were blown making several motors inoperable.”

As indicated previously, at Byron, a degraded voltage condition without a LOCA resulted in the undervoltage relays sounding an alarm in the control room and initiating a five minute timer. Based on the alarm response procedure, if the alarm was the result of a degraded voltage, the operators were required to call the grid operator to determine whether the grid voltage could be increased and monitor the bus voltage. If the voltage dropped below 75 percent, the operators were required to initiate a transfer of the loads to the emergency diesel generators. In comparison, with a LOCA present, the degraded voltage relays were set to automatically transfer the safety-related loads to the emergency diesel generators when the bus voltage dropped below 92.5 percent of the nominal voltage (4160 Volts).

The inspectors were concerned that, if the voltage at the 4 kV bus dropped to slightly above 75 percent of the nominal voltage, the operating motors would experience approximately a 28 percent increase in current, also considering the design voltage of the motors (4000 V). If operated within the design limits and properly protected, these motors would most likely experience no major damage. During the intervening five minutes, however, the increase in motor load current could result in spurious breaker trips and the automatic restart of the same or redundant motors with consequent further decrease in system voltages. At the lower voltage buses, the voltage drop would be greater than 25 percent due to losses in step-down transformers, cables, and other interposing devices. This voltage drop, complicated by potential motor starts, including the potential start of the motor-driven auxiliary feedwater pump, if a plant trip occurred, could result in adverse consequences that the licensee had failed to evaluate.

Discussions with the licensee regarding this issue indicated that the design was accepted by the NRC during the original review and provided a copy of the safety evaluation report (SER) issued by the NRC in February 1982. In the SER, it is stated that: “...if the degraded voltage is not corrected within 5 minutes, the bus will automatically disconnect from the offsite power source and connect to its onsite diesel generator. This is in conformance with the staff position and is, therefore, acceptable.”

Subsequently, in April 1989 following a meeting with the NRC to address the adequacy of the undervoltage protection scheme utilized at the Dresden Station, Commonwealth Edison (CECo) wrote to the NRC and “committed to implement administrative controls and associated operator training, which directs the operator to immediately take action to disconnect safety buses if the 4160 Volt power supply drops below 75 percent of the nominal bus voltage... The objective of this procedure is to minimize to less than one minute, if possible, the time that safety-related motors and other equipment could experience severe undervoltage (below 75 percent) in the extremely unlikely event that such conditions are sustained for more than several seconds.” This commitment was made for the five plants owned by CECO at the time of the meeting, including Byron. As in the SER case, the meeting minutes addressed only one variable, i.e., the minimum voltage level but not the duration. Therefore, it is not immediately evident that the NRC intended to accept a 75 percent voltage for five minutes. Furthermore, the meeting pertained to the Dresden plant and the design limitations may be different. The licensee

was unable to produce any documentation that was provided to the NRC in support of their design/operation of the electrical system.

The FSAR and the Technical Specification (TS) were consistent with the SER. They both acknowledged the existence of a five-minute timer, but neither the FSAR nor the TS bases addressed the voltage level at which the plants are allowed to operate for the specified period.

In response to the NRC concerns the licensee issued IR No. 892610. In the IR, the licensee indicated that they would develop a technical basis for the five minute delay. In the interim, they were revising the alarm procedure to direct the operator to separate the emergency buses from the system auxiliary transformer, upon confirmation that a degraded bus voltage condition (below 92.5 percent) existed.

This issue is considered unresolved pending: (1) evaluation of the licensee's technical basis for the time delay between the on-set of a degraded voltage condition and the transfer to the diesel generators, without a safety injection (SI) signal; and (2) discussion with NRR to determine the licensing and design basis (URI 05000454/455/2009007-04 (DRS)).

#### .4 Operating Experience

##### a. Inspection Scope

The inspectors reviewed five operating experience issues to ensure that NRC and industry generic concerns had been adequately evaluated and addressed by the licensee. The operating experience issues listed below were reviewed as part of this inspection:

- Westinghouse Technical Bulletin (TB) 06-2, "Aging Issues and Subsequent Operating Issues for Breakers That are at Their 20 Year Design/Qualified Life; UL certification/Testing Issues Update";
- IN 2008-18, "Loss of SR MCC caused by a Bus Fault";
- IN 2008-20, "Failure of MOV Actuators with Magnesium Alloy Rotors";
- IN 2006-22, "New Ultra Low Sulfur Diesel Fuel Oil Could Adversely Impact Diesel Engine Performance"; and
- IN 2008-02, "Findings Identified During Component Design Bases Inspections (Inspection Related Areas)."

##### b. Findings

A finding of low safety significance was identified during review of Westinghouse TB-06-02 (for details see Section 1R21.3.b(1) of this report).

#### .5 Risk Significant Operator Actions

##### a. Inspection Scope

The inspectors performed a margin assessment and detailed review of six risk-significant operator actions. These actions were selected from the licensee's PRA

rankings of human action importance based on risk achievement worth values. Where possible, margins were determined through a review of the assumed design basis and UFSAR response times and performance times documented by job performance measures results and by PRA analysis assumed operator response times. For the selected operator actions, the inspectors performed a detailed review and walk through of associated procedures. The inspectors also performed in plant observations for other important operator actions with a qualified senior reactor operator and an equipment operator to assess licensed operator and non-licensed operator knowledge level, adequacy of plant procedures, and the availability of special equipment required to perform the risk-significant operator actions out in the plant.

The following operator actions were reviewed:

- establish feed to steam generators (S/Gs) using motor/startup feedwater pumps;
- establish high/intermediate head ECCS pumps;
- isolate service water flooding in the auxiliary building before flooding the charging (CV) or emergency service water (SX) pump rooms;
- manually open air-operated valves (AOVs) IA-065 and IA-066;
- close SI-8806 or CV-112D and CV-112E or SI -8813 or SI-8814 or SI- 8920 valves during local emergency control of safe shutdown equipment; and
- effects on the operability evaluation for margin to S/G overfill following S/G tube rupture event.

b. Findings

No findings of significance were identified.

.6 Modifications

a. Inspection Scope

The inspectors reviewed 6 permanent plant modifications related to selected risk significant components to verify that the design bases, licensing bases, and performance capability of the components had not been degraded through modifications. The modifications listed below were reviewed as part of this inspection effort:

- EC 358165, "1A/B and 2A/B DG Over-current Protection";
- EC 370002, "Establish Criteria for ESF Battery Inter-Cell Connection Resistance";
- EC 366121, "Install Check Valve in OSX10BA-12 in Valve Chamber A-1";
- EC359963, "Revise Unit 2 Low Temperature Overpressure Protection System (LTOPS) Setpoints and Heatup/Cooldown Curves to Reflect Change to Pressure and Temperature Limitations Report (PTLR)";

- EC 364263, "Change to Ultra Low Sulfur Diesel Fuel (ULSD)"; and
- EC 366121, "Install Check Valve in 0SX10BA-12 in Valve Chamber A-1."

This activity is not considered an inspection sample.

b. Findings

No findings of significance were identified.

**4. OTHER ACTIVITIES**

4OA2 Identification and Resolution of Problems (71152)

.1 Routine Review of items Entered Into the CAP

a. Inspection Scope

The inspectors reviewed a sample of the selected component problems that were identified by the licensee and entered into the corrective action program. The inspectors reviewed these issues to verify an appropriate threshold for identifying issues and to evaluate the effectiveness of corrective actions related to design issues. In addition, corrective action documents written on issues identified during the inspection were reviewed to verify adequate problem identification and incorporation of the problem into the corrective action program. The specific corrective action documents that were sampled and reviewed by the inspectors are listed in the attachment to this report.

b. Findings

No findings of significance were identified.

4OA6 Management Meetings

1. Exit Meeting Summary

On March 27, 2009, the inspectors presented the inspection results to Mr. B. Adams, and other members of the licensee staff. The licensee acknowledged the issues presented. The inspectors confirmed that none of the potential report input discussed was considered proprietary.

The inspectors confirmed that none of the potential report input discussed was considered proprietary.

ATTACHMENT: SUPPLEMENTAL INFORMATION

## SUPPLEMENTAL INFORMATION

### KEY POINTS OF CONTACT

#### Licensee

B. Adams, Plant Manager  
C. Gayheart, Operations Manager  
S. Greenlee, Engineering Director  
V. Naschansky, Electrical/I & C Design Manager  
D. Gudger, Reg Assurance Manager  
T. Hulbert, Reg Assurance NRC Coordinator  
E. Blondin, Mechanical/Structural Design Manager  
B. Perchiazzi, Sr. Manager Designing Engineering  
B. Youman, WM Director  
M. Justice, System Engineer – counterpart  
E. Stender, System Engineer – counterpart  
A. Corrigan, System Engineer – counterpart  
A. Daniels, NOS Manager  
K. Passmore, Electrical Systems Manager  
M. Ryterski, System Engineer  
B. Quigley, System Engineer  
D. Sargent, System Engineer  
F. Lentine, Washington Group  
P. Simpson, Cantera Licensing  
L. Schofield, Cantera Licensing

#### Nuclear Regulatory Commission

A. M. Stone, Chief, Engineering Branch 2, (DRS)  
B. Bartlett, Senior Resident Inspector  
J. Robbins, Resident Inspector  
M. Abid, Reactor Inspector, Observer  
J. Dalzell, Inspector in Training  
J. Corujo-Sandin, Inspector in Training

**LIST OF ITEMS OPENED, CLOSED AND DISCUSSED**

Opened

05000454/455/2009007-01	NCV	Failure to Maintain/Extend the Qualification Basis for Molded-Case Circuit Breakers (MCCBs) Used in Safety-Related Applications Greater than 20 Years. (1R21.3.b.(1))
05000454/455/2009007-02	NCV	Inadequate Analysis of Molded-Case Circuit Breaker Test Data. (1R21.3.b.(2))
05000454/455/2009007-03	URI	Concerns with Licensee's Margin to Overfill (MTO) Analysis Related to Steam Generator Tube Rupture (SGTR) Event. (1R21.3.b.(3))
05000454/455/2009007-04	URI	Insufficient Design Bases for Second-Level (Degraded) Voltage Timer Settings. (1R21.3.b.(4))

Closed

05000454/455/2009007-01	NCV	Failure to Maintain/Extend the Qualification Basis for Molded-Case Circuit Breakers (MCCBs) Used in Safety-Related Applications Greater than 20 Years. (1R21.3.b.(1))
05000454/455/2009007-02	NCV	Inadequate Analysis of Molded-Case Circuit Breaker Test Data. (1R21.3.b.(2))

## LIST OF DOCUMENTS REVIEWED

The following is a list of documents reviewed during the inspection. Inclusion on this list does not imply that the NRC inspectors reviewed the documents in their entirety, but rather, that selected sections or portions of the documents were evaluated as part of the overall inspection effort. Inclusion of a document on this list does not imply NRC acceptance of the document or any part of it, unless this is stated in the body of the inspection report.

### AUDITS, ASSESSMENTS AND SELF-ASSESSMENTS

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
FASA # 780286	Readiness Review for 2009 NRC Component Design Basis Inspection (and associated corrective action Items)	11/21/08

### CALCULATIONS

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
BYR03-097	Safety Injection Strong Pump/Weak Pump Interaction on Recirculation Flow	0
BYR04-016/ BRW04-0005-M	RHR, SI, CV, and CS Pump NPSH During ECCS Injection Mode	1, 1A, 2
BYR2000-189	Byron Unit 2 Low Temperature Overpressure Protection (LTOP) System	1
CE-BB-001	MOV Seismic Qualification	1
CE-BB-003	MOV Seismic and Weak Link Analysis for Jamesbury 24" Butterfly Valves	0
NED-M-MSD-13	Seismic Qualification Reevaluation due to Increased Operating Loads (Thrust/Torque) for the MOV's Listed in Table 1 of this Calculation	0
NED-M-MSD-98	Seismic Qualification Reevaluation of the MOV's Listed Below	0
V-EC-1622	PORV Block Valve Stem Assembly Analysis	2
BYR-2SX007	MIDACALC AC Motor Operated Butterfly1 Valve Calculation	6
BYR-2RY8000A	MIDACALC AC Motor Operated Gate Valve Calculation	4
BYR-2AF013H	MIDACALC AC Motor Operated Globe Valve Calculation	2
002-M015	Reactor Press Sys (RY) MOV Differential Press	1
002-M027	AF System MOV Differential Pressure Calculations	1
002-M-034	Byron U2 AF System Diff Press	1
002-M-068	SX Differential Pressure Calc.	2

## CALCULATIONS

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
AOV-MARG-BYR 1/2RY455A/456	Pressurizer Power Operated Relief Valves	0
AOV-MEDP-BYR 1/2RY455A/456	Pressurizer Power Operated Relief Valves	0
1-RY-79	Cat. I N <sub>2</sub> Supply Tanks for PORV Actuator	1
95-111	Verification of Capability for Braidwood and Byron 3" 1(2)RY8000A & B Valves Susceptible to Pressure Locking	1
PSA-B-9808	Byron/Braidwood ECCS Flow Calculations for Safety Analysis	3C
BYR97-441	Essential Service Water Make-up Pump Head Caalculatation	3B
BYR98-185	Essential Service Water Makeup Pump Diesel Oil Storage Tank Minimum Level	0A
BYR98-224	Fire Pumps 0FP03PA and 0FP03PB Recirculation Test Line Hydraulic Characterization	0
BYR98-234	Essential Service Water Makeup System Overpressure Evaluation for Pump Impeller Replacement	0A
BYR99-006	Essential Service Water Makeup System Maximum Operating Pressure	0
BTR03-095	Auxiliary Feedwater Strong Pump/Weak Pump Interaction on Recirculation Flow	0
BYR04-043	Documentation of Adequate NPSHa for AF Pumps when Supplied from CSTs	1
NED-I-EIC-0186	Auxiliary Feedwater Pump Suction Pressure Setpoint Error Analysis	2
NED-M-MSD-014	Byron Ultimate Heat Sink Cooling Tower Basin Makeup Calculation	8A
PSA-B-97-14	Evaluation of New CST Technical Specification Levels for Byron Station	1
PSA-B-97-18	Byron/Braidwood AFW Flow for AF005A-H Modification	5B
PSA-B-98-05	Analysis of FW Pump Suction Transients using the SX Water Supply for Byron and Braidwood Stations	0
PSA-B-00-04	Byron/Braidwood Steam Generator Tube Rupture Analysis for Power Uprate	3D
SX1-89	Available NPSH for AF Pump when Supplied from SX System	1
VD-100	Diesel Generator Room Energy Loads	0
AK-4	ELMS-AC PLUS Project Specific Implementation	2
AK-4	ELMS-AC PLUS Project Specific	2A

## CALCULATIONS

<u>Number</u>	<u>Description or Title</u> Implementation	<u>Date or Revision</u>
19-AN-7	Protective Relay Setting for 4.16 kV ESF Switchgear	11
19-AN-7/EC-365206	Protective Relay Setting for 4.16 kV ESF Switchgear	11A
19-AN-7/EC-368519	Protective Relay Setting for 4.16 kV ESF Switchgear	11B
19-AN-28	Relay Setpoint	1
19-AQ-63	Division Specific Degraded voltage Analysis	6
19-AU-5	480 V Unit Substation and Relay Settings	013
19-T-5	Diesel generator Loading During Loop/LOCA – Byron Units 1 & 2	6
BYR01-086	Motor Operated Valves Actuator Motor Terminal Voltage and Thermal Overload Sizing Calculation – Auxiliary Feedwater System (EC#343313)	06/19/03
BYR01-093	Motor Operated Valves Actuator Motor Terminal Voltage and Thermal Overload Sizing Calculation – Reactor Coolant Pressurizer System (EC#343313)	06/19/03
BYR01-095	Motor Operated Valves Actuator Motor Terminal Voltage and Thermal Overload Sizing Calculation – Essential Service Water System (EC#343313)	06/19/03
BYR2000-136	Voltage Drop Calculation for 4160V Switchgear Breaker Control Circuits	000B
BYR2000-191	Voltage Drop Calculation for 480V Switchgear Breaker Control Circuits	0
SL 102	Short Circuit Summary for High Voltage Buses	03/05/09
SL 102	Short Circuit Summary for Low Voltage Buses	03/12/09
SL 104	Load Summary by Bus	02/24/09
SL 108	Load Ticket	02/24/09
BYR97-204	125 VDC Battery Sizing Calculation	3H
BYR97-205	125 VDC Battery Charger Sizing Calculation	2
BYR97-224	125 VDC Voltage Drop Calculation	2C
BYR97-225	Circuit Breaker Trip Settings – 125 V DC and 250 V DC Distribution Centers	1
BYR97-226	125V DC System Short Circuit Calculation	2
BYR97-227	125 V DC Fuse Sizing and Coordination	0
NED-H-MSD-17	Verification of Byron 125 VDC Battery Room 111, 112, 211, & 212 Ventilation Requirements and Hydrogen Concentration Evaluation following a Loss of Battery Room Ventilation	2

**CALCULATIONS**

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
---------------	-----------------------------	-------------------------

**CONDITION REPORTS GENERATED DURING INSPECTION**

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
---------------	-----------------------------	-------------------------

884719	Air Hose 2B DG Room Seismic Housekeeping	2/23/09
885117	OFP03EB Spilled Liquid on Battery	2/25/09
885120	OFP3EA Spilled Liquid on Battery	2/25/09
885153	OFP3EA Over-tightened Battery Connection	2/25/09
885160	OFP3EB Over-tightened Battery Connection	2/25/09
885221	Corrosion on Battery Connection	2/25/09
885481	OPC FP 8021 Cont Door Open	2/25/09
885493	Heavy Oil Accumulation	2/25/09
885764	Non Conservative Input SGTR MTO Calc.	2/25/09
885898	PZR PORV 1RY456 Accum Press Ind	2/26/09
888981	Cosider Setting Calc. 1-RY-79 to Historical	3/4/09
889740	MCCB Service Life W TB 06-2	3/6/09
890902	2RY8000A DP Calc. Does Not Match Ops Procedure	3/10/09
892033	Perform Monitoring UT on )SX10AB-8	3/12/09
892066	AF013S Use of Lower SX Min Flow Rate	3/12/09
892124	SER PA0335 Indication Actions Not Closed	3/12/09
892204	ACB 2424 UV Relay Not Calibrated Per PCM	3/12/09
892238	Relay Left OOT After Cal Check in 2007	3/12/09
892610	Degraded Voltage 5-Minute Timer	3/13/09
893423	1/2RY8000A/B IST Testing Requirements	3/16/09
894173	Unplanned LCOAR-1RY8000A/B Missed	3/17/09

**CONDITION REPORTS GENERATED DURING INSPECTION**

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
894182	Surveillance Missed IST Surveillance for 1/2RY8000A/B	3/17/09
897354	Preliminary NRC Information on Single Failure for SGTR MTO	3/25/09
897507	Incomplete Press test on Buried Portion of 0SX10BA-12	3/25/09
897537	2009 CDBI Issue AC Power Feed to River Screen House	3/25/09
897630	CDBI 2009 Byron Inspection Breaker Testing Issues	3/25/09
897901	CDBI 2009 NRC Question Regarding Aux Power Pre-op Test	3/26/09
898000	CDBI 2009 Issue AF Suction Pressure Calculation Enhancement	3/26/09
898543	CDBI 2009 Westinghouse TB 06-02 Review Issue	3/27/09
907731	OOT Safety-Related HFB Breakers Installed Since 09/2003	4/15/09

**CORRECTIVE ACTION PROGRAM DOCUMENTS REVIEWED**

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
IR00219364	2SX007 Troubleshooting	05/06/04
IR00553165	2SI01PA Minor Leak	11/03/06
IR00562375	Calculation BYR04-016 Assumptions	11/27/06
IR00582390	Dry Boric Acid on 2SI01PA Inboard and Outboard Seals	01/23/07
IR00834601	Failed PMT 2RY089A Body to Bonnet Leak	10/23/08
IR00844445	Closing DP for CS001S	11/13/08
IR00876545	UFSAR Table 6.3-1 - Data on SI Pump Max Flow Rate not Correct	02/05/09
IR00880087	Math Error Found in Calc. BYR04- 016/BRW-04-0005-M	02/12/09
IR00882992	Calc Input Document Revised Without Revising Affected Calc	02/20/09
IR00885898	PZR PORV 1RY456 Accumulator Pressure Indication	02/26/09
IR00888981	Consider Setting Calc. 1-RY-79 to Historical	02/26/09
IR00890902	2RY8000A DP Calc Doesn't Match OPS Procs	03/10/09
IR00892066	AF013S, Use of Lower SX Min Flow Rate	03/12/09
IR00892124	SER PA0335 Indication Actions Not Closed	03/12/09
IR00893423	1RY8000A/B PZR PORV Block Valves IST	03/16/09

**CORRECTIVE ACTION PROGRAM DOCUMENTS REVIEWED**

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
	Testing Requirements	
IR00894182	Unplanned LCOR 1RY8000A/B Missed Surveillance	03/17/09
IR00897354	Missed Surv for 1/2RY8000A/B	03/17/09
IR 00534749	Potential Issues with the Use of Ultra Low Sulfur in EDGS	9/22/06
IR 00553007	MNTC River Cleaning Not Performed per WO, WO Closed	11/3/06
IR 00680419	SG PORV TS Inappropriately Credits Local Ops for SGTR	10/5/07
IR 00687783	B1F24/B2F25 SG PORV Operability Concern	10/22/07
IR 00706293	Byron/Braidwood SGTR Issues	12/2/07
IR 00713904	Independent Review of Byron/Braidwood SGTR Analysis	12/19/07
IR 00885493	NRC Identified Heavy Oil Accumulation on Floor	2/26/09
IR 00885764	Non-Conservative Input to SGTR MTO Calculation	2/26/09
	Perform Monitoring UT on 0SX10AB-8	3/12/09
IR 00892033		
IR 00892079	A Change to Commitment Letter 90-08400 is Needed	3/12/09
IR 00897354	Preliminary NRC Info on Single Failure for SGTR MTO	3/25/09
IR 00897507	Incomplete Pres. Test on Buried Portion of 0SX10BA-12	3/25/09
IR 00897537	AC Power Feed to the River Screen House	3/25/09
IR 00898000	AF Suction Pressure Calculation Enhancement	3/26/09
IR 00222741	Byron Station Review of OE 18379	05/21/05
IR 00142997	Problems Encountered During 0B SX M/U Pump PMT Run	02/05/03
IR 00460657	0B SX M/U Pump ASME Test Trending Results: Negative Trend	03/01/06
IR 00722780	0B SX Makeup PP Loss of Discharge Pressure	01/16/08
IR 00811213	0BVSR SX-5 Failed Surveillance	08/26/08
IR 00754582	U-2 Loss of Power (SAT 242-2)	03/05/08
IR 00840841	Lesson Learned from SAT 242-2 Inability to Energize	11/05/08
IR 00755204	Failed Insulator at 4KV Non-Seg Duct for SAT 242-2	03/27/08
	NRC Concern on SAT 242-2 Trip when Energized	05/01/08
IR 00770417		

**CORRECTIVE ACTION PROGRAM DOCUMENTS REVIEWED**

<b><u>Number</u></b>	<b><u>Description or Title</u></b>	<b><u>Date or Revision</u></b>
IR 00863768	0B SX M/U Pump Failed to Start	01/07/09
IR 00672566	Non-Conservatism in Steam Generator Tube Rupture Methodology	09/17/07
IR 00664901	NRC IN 2006-26 Failure of MOV Magnesium Rotors	08/27/07
IR 00678340	NER NC-07-039 Yellow – MOV Motor Magnesium Rotor Degradation	10/01/07
IR 00770829	2SI8812B - Motor Found Degraded Per Inspection Criteria	05/01/2008
IR 00780768	Charger 212 AC Input Breaker Trip	
IR 00846420	2SI8811A - Motor Found Degraded Per Inspection Criteria	11/18/08
IR 00855267	IN-2008-20 MOV Motor Actuator Magnesium Rotor Failure	03/06/09
IR 00884719	Seismic Housekeeping Issue	02/24/09
IR 00892204	ACB 2424 UV Relay Not Calibrated per PCM Template Frequency	03/12/09
IR 00892238	Relay Left Out of Tolerance After Cal Check in 2007	03/12/09
IR 00892610	Degraded Voltage 5-Minute Timer	03/13/09
IR 00897901	NRC Question Regarding Aux Power Pre- Op Test	03/26/09
IR 00261584	Battery 212 Voltage Below Admin Limit	10/08/04
IR 00279918	Battery Cells Exceed Acceptance Criteria	12/07/04
IR 00286758	Bus 212 Voltage Appears to be Degraded	12/31/04
IR 00359168	Battery Charger 212 Voltage Fluctuations	08/02/05
IR 00359353	Charger Malfunction During PED Surveillance	08/03/05
IR 00496936	Five Battery Cells Fail Resistance Readings	06/05/06
IR 00546831	Battery Connection Resistance	10/20/06
IR 00550699	Battery Connection Resistance Discrepancy	10/29/06
IR 00573536	Resistance Readings > 50 Microohms	12/28/06
IR 00586759	Bus 212 Charger Load Test	02/01/07
IR 00634228	DC Bus 212 Bus Voltage and Battery Voltage Drop over 2 Days	05/27/07
IR 00652507	212 Battery and Bus Voltage Below Rounds Spec	07/22/07
IR 00657890	Unplanned LCOAR Entry on DC Bus 212 Battery	08/07/07
IR 00679646	DC Battery 212 Terminal Voltage Below Admin Limit	10/03/07
IR 00688564	DC212 Battery Charger Output Drifting Lower	10/24/07
IR 00696602	DC Bus 212 Voltage Above Admin Limit	11/08/07

**CORRECTIVE ACTION PROGRAM DOCUMENTS REVIEWED**

<b><u>Number</u></b>	<b><u>Description or Title</u></b>	<b><u>Date or Revision</u></b>
IR 00698860	DC 212 Charger Upper Voltage Limit for Rounds	11/14/07
IR 00705355	DC Amps Fluctuating	11/30/07
IR 00767523	Unexpected Alarm - - DC Bus 212 Grounds	04/25/08
IR 00772962	Unexpected DC Ground During 2B DG Run	05/07/08
IR 00780768	Charger 212 AC Input Breaker Trip	05/29/08
IR 00794566	Documentation of Specific Battery Cells found in IR 794565	07/08/08
IR 00818375	212 DC Battery Voltage Low	09/16/08
IR 00828237	Battery 212 Pilot Cell Surveillance Admin Limit Exceeded	10/08/08
IR 00840951	U2 Unexpected Alarm 2-22-D6 "125 VDC Bus 212 Ground"	11/05/08
IR 00867508	DC 212 Battery Terminal Voltage Greater than Admin Limit	01/15/09
IR 00870481	Battery Voltage Higher than Admin Limit	01/23/09
IR 00873857	212 Battery Terminal Voltage Slightly > than the Admin Limit	01/29/09
IR 00877156	DC Bus 212 Battery Terminal Voltage Above Admin Limit	02/06/09
IR 00880367	DC 212 Ground	02/13/09
IR 00884090	Unexpected Alarm 1-21-D6 "125VDC Bus 111 Ground"	02/23/09

**DRAWINGS**

<b><u>Number</u></b>	<b><u>Description or Title</u></b>	<b><u>Date or Revision</u></b>
D-268832	Model D-100-160 Actuator 3" Class 1500 Valve Assembly	10
M-42, sheet 2B	Diagram of Essential Service Water	AV
M-135, sheet 5	Diagram of Reactor Coolant	AL
M-135, sheet 8	Diagram of Reactor Coolant	AB
M-136, sheet 1	Diagram of Safety Injection	AV
M-136, sheet 3	Diagram of Safety Injection	AL
Q6049, sheet 75	PORV Accumulator Tank	J
M-37	Diagram of Auxiliary Feedwater	AX
M-97	Diagram of Generator Room 1A & 1B Ventilation System	P
M-122	Diagram of Auxiliary Feedwater	AX
M-124	Diagram of Condensate	AX
M-553	Condensate Makeup System	M
6E-2-4030AF07	Byron Unit 2, Schematic Diagram- Steam Generator 2A, Auxiliary Feedwater Isolation Valves 2AF013A from Pump 2A & 2AF013E	H

## DRAWINGS

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
	from Pump 2B	
6E-2-4030AF08	Byron Unit 2, Schematic Diagram- Steam Generator 2B, Auxiliary Feedwater Isolation Valves 2AF013B from Pump 2A & 2AF013F from Pump 2B	H
6E-2-4030AF09	Byron Unit 2, Schematic Diagram- Steam Generator 2C, Auxiliary Feedwater Isolation Valves 2AF013C from Pump 2A & 2AF013C from Pump 2B	H
6E-2-4030AF10	Byron Unit 2, Schematic Diagram- Steam Generator 2D, Auxiliary Feedwater Isolation Valves 2AF013D from Pump 2A & 2AF013H from Pump 2B	H
6E-1-4030MS39	Schematic Diagram Steam Generator 1A Atmospheric Relief Valve 1MS018A Modulation & Control	T
6E-2-4030RY17	Schematic Diagram Pressurizer Power Relief Valves- 2RY455A	L
6E-2-4030SX27	Schematic Diagram Component Cooling Heat Exchanger 2 Outlet Valve 2SX007	F
6E-0-3322	Electrical Installation Auxiliary BLDG. Plan ELEV. 383'-0"	DH
6E-0-3322CTS	Conduit Tabulation Aux. Bldg. PLAN EL. 383'-0"	X
6E-0-3322D07		BC
6E-0-3659	Cable Pans Routing, Auxiliary BLDG. Plan EL. 383'-0"	AJ
6E-0-3664	Cable Pans Routing, Auxiliary BLDG. Plan EL. 401'-0"	AJ
6E-0-3668	Cable Pans Routing, Auxiliary BLDG. Plan EL. 426'-0"	AE
6E-2-4030RY12	Schematic Diagram Pressurizer Relief Isolation Valves 2RY8000A & 2RY8000B	L
6E-0-3666	Byron- Unit 1&2 Cable Pans Routing, Auxiliary Bldg. PLAN ELEV. 414'-0"	AE
6E-2-3342	Electrical Installation Auxiliary Bldg Plan EL. 414'-0"	BR
6E-2-3342CT1	Conduit Tabulation Auxilliary Bldg, Plan Elevation 414'-0"	BE
6E-2-3657		P
6E-2-3544	Electrical Installation Reactor Building, Plan EL. 412'-0" Loop 4	BS
6E-2-3544CT1	Conduit Tabulation Reactor Bldg, Plan EL. 412'-0", Loop 4	AK
6E-2-3554D01		Y

**DRAWINGS**

<b><u>Number</u></b>	<b><u>Description or Title</u></b>	<b><u>Date or Revision</u></b>
6E-2-3591 Sht. 1	Electrical Installation Reactor Bldg.- Sections, Pressurizer Enclosure Ext EL. LP4	AE
6E-2-3554CT1	Conduit Tabulation Reactor Bldg. Plan EL. 426'-0" LOOP 4	AE
6E-2-3554CT2	Conduit Tabulation Reactor Bldg. Plan EL. 426'-0" LOOP 4	AC
6E-2-4030DG03	Schematic Diagram, Diesel Gen 2B Fuel Oil Transfer Pump 2D01PB & 2D01PD	G
6E-2-3305	Electrical Installation Aux. Feedwater Pipe Tunnel Plan, Part 2	AC
6E-2-3305CT1	Conduit Tabulation, Aux. Feedwater Pipe Tunnel Plan, Part 2	P
6E-3306	Electrical Installation, Aux. Feedwater Pipe Tunnel Sections	P
6E-2-3301	Electrical Installation Aux. Feedwater Pipe Tunnel Plan, Part 1	AB
6E-2-3301CT1	Conduit Tabulation Auxiliary Feedwater Pipe Tunnel Plan, Part 1	P
6E-0-3303	Electrical Installation Aux. Bldg Plan EL.346'-0", Cols L-Q, 21-26	CD
6E-0-3652	Cable Pan Routing, Auxiliary Bldg. El. 346'- 0", Cols. L-Q, 18-26	T
6E-0-3654	Cable Pan Routing, Auxiliary Bldg. Plan El. 346'-0", Cols. Q-Y, 18-26	O
6E-2-4842C	Internal/ External Wiring Diagram Air Operated Valves "RY" System Junction Boxes Part 3	G
6E-2-3544	Electrical Installation Reactor Building Plan El. 412'-0" Loop 4	BS
6E-2-3554	Electrical Installation Reactor Building Plan EL. 426'-0" Loop 4	BG
6E-2-3554CT1	Conduit Tabulation Reactor Building Plan EL. 426'-0", Loop 4	AE
6E-2-3554CT2	Conduit Tabulation Reactor Building Plan EL. 426'-0" Loop 4	AC
6E-2-3554D01	Electrical Installation Reactor Building Section & Details	Y
6E-2-3591 sh. 1	Electrical Installation Reactor Building- Sections Pressurizer Enclosure Ext. EL. LP 4	AE
6E-2-3591 sh. 2	Electrical Installation Reactor Building Enclosure Interior EL. Loop 4	N
6E-2-3343 sh. 1	Electrical Installation Auxiliary Building Plan EL. 414'-0", COLS. Q-S. I; 25-29	AP
6E-2-3343CT1	Conduit Tabulation Auxiliary Building Plan	AR

**DRAWINGS**

<b><u>Number</u></b>	<b><u>Description or Title</u></b>	<b><u>Date or Revision</u></b>
6E-2-3343D01	EL. 414'-0", Columns Q-S.1; 25-29 Electrical Installation Auxiliary Building Elevation 414'-0" Sections	AB
6E-2-3353 sh. 1	Electrical Installation Auxiliary Building Plan EL. 426'-0", Columns Q-S, 25-29	AT
6E-2-3353CT1	Conduit Tabulation Auxiliary Building Plan El. 426'-0"	AT
6E-2-3353D01	Electrical Installation Auxiliary Building Sections and Details	AF
6E-2-3363 sh. 3	Electrical Installation Auxiliary Building Plan EL. 439'-0", Columns N-Q, 25-26	D
6E-2-3363CT3	Conduit Tabulation Auxiliary Building Plan EL. 439'-0", Columns L-Q, 23-26	S
6E-2-3363D01	Electrical Installation Auxiliary Building Sections and Details	AB
6E-0-3373D	Electrical Installation Auxiliary Building Plan EL. 451'-0", Columns 23-25, M-Q	CZ
6E-0-3373CT3	Conduit Tabulation Auxiliary Building EL. 451'-0"	AA
6E-0-3383	Byron- Units 1 & 2 Electrical Installation Aux. Bldg. Plan EL. 463'-5", COLS. N-Q, 23- 25	C
6E-0-3383CT3	Conduit Tabulation Auxiliary Building Plan Elev. 463'-5"	AQ
6E-0-3688C	Cable Pans Routing Auxiliary Building Plan EL. 463'-5", Columns L-Q, 18-26	AC
6E-0-3664	Cable Pans Routing Auxiliary Building Plan EL. 401'-0", Columns L-Q, 18-29	AJ
6E-0-3666	Byron- Units 1 & 2 Cable Pans Routing Auxiliary Building Plan EL. 414'-0", Columns Q-Y, Rows 18-29	AE
6E-2-3657	Cable Pans Cable Reactor Bldg. Plan El. 412'-0"	P
6E-0-4000	One Line 345KV Bus Diagram	E
6E-0-4001	Station One Line	K
6E-0-4030CC01	Schematic Diagram Component Cooling Pump 0 (Div 11)	U
6E-0-4030CC02	Schematic Diagram Component Cooling Pump 0 (Div 12)	V
6E-0-4030CC03	Schematic Diagram Component Cooling Pump 0 (Div 21)	Q
6E-0-4030CC04	Schematic Diagram Component Cooling Pump 0 (Div 22)	O
6E-0-4030CC05	Schematic Diagram Component Cooling Pump 0 (Div 11)	N

**DRAWINGS**

<b><u>Number</u></b>	<b><u>Description or Title</u></b>	<b><u>Date or Revision</u></b>
6E-0-4030CC06	Schematic Diagram Component Cooling Pump 0 (Div 12)	Q
6E-0-4030CC07	Schematic Diagram Component Cooling Pump 0 (Div 21)	N
6E-0-4030CC08	Schematic Diagram Component Cooling Pump 0 (Div 22)	N
6E-0-4030FP02	Schematic Diagram Diesel Driven Fire Pump OB Controller	F
6E-0-4030FP03	Schematic Diagram Diesel Driven Fire Pump OB Annunciator Alarms	D
6E-0-4030SX10	Schematic Diagram Essential Service Water Make-Up Pump OB	P
6E-0-4030SX25	Schematic Diagram Essential Service Water Make-Up Pump OB Control Cabinet	T
6E-0-4615A	Internal/External Wiring Diagram 4160V CC Pump 0 SWGR Cub 1	F
6E-0-4615B	Internal/External Wiring Diagram 4160V CC Pump 0 SWGR Cub 2	G
6E-0-4615C	Internal/External Wiring Diagram 4160V CC Pump 0 SWGR Cub 3	H
6E-0-4615D	Internal/External Wiring Diagram 4160V CC Pump 0 SWGR Cub 4	G
6E-1-4001A	Station One Line diagram	O
6E-1-4008G	Key Diagram 480V Aux, Bldg. ESF MCC 131X2B	J
6E-1-4008J	Key Diagram 480V Auxiliary Building ESF MCC 131X1	AG
6E-1-4008AC	Key Diagram 480V Aux, Bldg. ESF MCC 132X5	W
6E-1-4030MS39	Steam generator 1A Atmospheric Relief Valve 1MS018A Modulation & Control	T
6E-1-4843E	Internal/External Wiring Diagram Computer Input Thermocouple - CC System	C
6E-2-4001A	Station One Line Diagram	N
6E-2-4002C	Single Line Diagram 4.16KV SWGR Bus 241 & 243 Diesel Gen 2A & 480V SWGR	O
6E-2-4002D	Single Line Diagram 4.16KV SWGR Bus 242 & 244 Diesel Gen 2B & 480V SWGR	N
6E-2-4006A	Key Diagram 4160V ESF SWGR Bus 241	E
6E-2-4006B	Key Diagram 4160V ESF SWGR Bus 242	E
6E-2-4018B	Relay and Metering Diagram ESF SWGR Bus 242	R
6E-2-4029AP15	Control Logic Diagram ESF SWGR Bus 241, 242 Undervoltage Relays	B
6E-2-4030AF01	Schematic Diagram Auxiliary Feedwater	Y

## DRAWINGS

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
	Pump 2A	
6E-2-4030AF10	Schematic Diagram Steam Generator 2D Auxiliary Feedwater Isolation Valves 2AF013D From Pump 2A & 2AF013H From Pump 2B	H
6E-2-4030AP32	Schematic Diagram System Aux Transformer 242-2 Feed to 4.16KV ESF SWGR Bus 242-ACB 2422	U
6E-2-4030AP34	Schematic Diagram Reserve Feed From 4.16KV ESF SWGR Bus 142 To 4.16KV ESF SWGR Bus 242-ACB 2424	V
6E-2-4030AP35	Schematic Diagram Bus Tie Breaker ACB #2421 (4.16KV ESF SWGR Bus 242 to 4.16KV Bus 244)	Q
6E-2-4030AP39	Schematic Diagram 4.16KV ESF SWGR Bus 242 Undervoltage Relays PR29A-427- B242 & PR29C-427-B242, P5A-427-ST22 & PR5C-427-ST22	P
6E-2-4030CC02	Schematic Diagram Component Cooling Pump 2B	N
6E-2-4030DG02	Schematic Diagram Diesel Generator 2B Feed to 4.16KV ESF SWGR Bus 242-ACB 2423	T
6E-2-4030DG51	Schematic Diagram Diesel Generator 2B Starting Sequence Control 2DG01KB Part-1	AH
6E-2-4030DG52	Schematic Diagram Diesel Generator 2B Starting Sequence Control 2DG01KB Part-2	AE
6E-2-4030DG58	Schematic Diagram Diesel Generator 2B Control & Alarm Signal Contacts 2DG01KB	K
6E-2-4030RY12	Schematic Diagram Pressurizer Relief Isolation Valves 2RY8000A & 2RY8000B	L
6E-2-4030SI02	Schematic Diagram Safety Injection Pump 2B	H
6E-2-4030SX27	Schematic Diagram Component Cooling Heat Exchanger 2 Outlet Valve 2SX007	F
6E-2-4612A	Elevation 4160V SWGR Bus 242 (Div. 22)	J
6E-2-4637A	Internal/External Wiring Diagram 480V, ESF Substation 232X (2AP13E)	G
6E-2-4637B	Internal/External Wiring Diagram 480V, ESF Substation 232X (2AP12E)	P
6E-0-4001	Station One Line Diagram	L
6E-2-4002F	Single Line Diagram 120V AC ESF Instrument Inverter Bus 212 & 214 125 V DC ESF Distribution Center 212	F
6E-2-4030DC02	Schematic Diagram 125 VDC Battery	M

**DRAWINGS**

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
6E-2-4030DC08	Charger 212 2DC04E Schematic Diagram 125 VDC ESG Dist Center Bus 212 (2DC06E) Part 1 & 125 VDC ESF Dist PNL 212 (2DC06EA) Front	R
6E-2-4030DC09	Schematic Diagram 125V DC ESF Dist. Center Bus 212 (2DC06E) Part 2 & 125V DC ESF Dist. Pnl 212 2DC06E (Rear)	P
6E-2-4030DC10	Schematic Diagram 125V DC ESF Dist. Center Bus 212 (2DC06E) Part 3 & 125V DC Non-Safety Related Dist. Pnl 214 (2DC06EB)	K

**MISCELLANEOUS**

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
	Letter from Cope Vulcan: Commonwealth Edison Contract Number 00012175	06/02/00
	Letter from Ingersoll-Dresser Pump Company: Minimum Flow Tolerances	06/21/00
	Byron Unit 2 – Pressure and Temperature Limits Report (PTLR)	12/06
NDIT BYR 97-279	Certified Performance Curve for SI Pump	07/03/97
OP-AA-108-111	Pressurizer PORV Accumulator Pressure Monitoring	03/02/09
ER-AA-321 Att. 4, Report 08-031	IST Pump Evaluation Form – Comprehensive Test 2SI01PA	10/18/08
ER-AA-321 Att. 4, Report 08-037	IST Pump Evaluation Form – Group A Test 2SI01PA	11/07/08
BB-SURV-001	Risk Assessment Missed Surveillance – 1(2)RY800A(B) Failure to Time the Open Stroke	1
DG96-000188	GL 89-10 Program MOVs' Records for Byron Station	02/09/96
BPM #1363	Loop Seal/Vent for Auxiliary Feedwater Pumps Suction Line	10/29/91
ComEd Letter	Steam Generator Tube Rupture Analysis	10/12/84
ComEd Letter	Steam Generator Tube Rupture Analysis	1/21/87
ComEd Letter	Steam Generator Tube Rupture Analysis	4/25/90
ComEd Letter	Steam Generator Tube Rupture Analysis	11/13/96
ComEd Letter	Revised Steam Generator Tube Rupture Analysis	6/24/97
NRC Letter	Steam Generator Tube Rupture Analysis	4/19/84
NRC Letter	Acceptance for Referencing of Licensing	3/30/87

**MISCELLANEOUS**

<b><u>Number</u></b>	<b><u>Description or Title</u></b>	<b><u>Date or Revision</u></b>
	Topical Report WCAP-10698	
NRC Letter	Seismic Qualification of Byron Deep Wells	8/7/89
NRC Letter	Steam Generator Tube Rupture Analysis	4/23/92
NRC Letter	Information Regarding Revised Steam Generator Tube Rupture Analysis	5/20/97
NRC Letter	Revised Steam Generator Tube Rupture Analysis	1/28/98
NRC Letter	Revised Steam Generator Tube Rupture Analysis	5/25/99
System Health Report	Auxiliary Feedwater (10/1/08 – 12/31/08)	N/A
System Health Report	Diesel Generators (10/1/08 – 12/31/08)	N/A
System Health Report	Essential Service Water (10/1/08 – 12/31/08)	N/A
System Health Report	Fire Protection (10/1/08 – 12/31/08)	N/A
L200-0495	Limitorque (Flowserve)- Technical Update 06-01 Reliance Motors/ Magnesium Rotors	12/26/06
B260-0026	Sulzer Pumps As Found Report for PO #00430485 M/U Water Pump Seal Box & Mech Seal Gland job #08C02838 S/N NJ-1945/46	01/16/08
B260-0027	Sulzer Pumps As Left Report for PO #00430485 M/U Water Pump Seal Box & Mech Seal Gland job #08C02838 S/N NJ-1945/46	01/16/08
J105-0001	IOM Manual- Provide allowance to increase ID of disaster bushing from 2.021" to 2.040 + .000/ -.0002 inches per EC #368774	02/27/08
J105-0001	IOM Manual – Revision to Bill of Material 99034 Rev 89, pages 1 thru 11, Order #NJ-1945/6, includes Rev Notice dated 2/7/83 Byron Station Unit 2 Loss of Off-Site Power Event, March 25, 2008, Root Cause Report	04/05/07
2AP155-1	Inter-Office Memorandum – Safety-Related/Non-Safety-Related Interface Review report	01/06/82
ER-AA-310-1005	A1 Determination Issue Report No. 752113 Byron and Braidwood Stations- Station Blackout Analysis Pages 4-3 to 4-6 Motor Data Sheets for RHR, SI and CV Pump Motors	04/16/08

**MISCELLANEOUS**

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
35605, 262-NH-43278-01, N-1028, A-22881, 0VA02CA-D	Pump/Motor performance Curves for SX, CV CS and CC pumps and VA exhaust Fan	
	Diesel Generators 2B Loading Test performance Curves	10/14/08
	Diesel Generators 1A Loading Test performance Curves	04/06/08
SOER 99-01	Loss of Grid Addendum Byron Station – Unit 1 & 2 Braidwood Station – Units 1 & 2 Station Blackout Study	09/25/92

**OPERABILITY EVALUATIONS**

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
EC 367065	Op Eval 07-007, Main Steam PORV Steam Relief Capacity	2
EC 367423	Evaluation of Decay Heat Impact on the SGTR Analysis	0
OE 22825	Improper Configuration of DC Lighting Results in Overload of Station Batteries	07/21/06

**PROCEDURES**

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
0BOSR 10.b.1-1	Fire Suppression System Contained Water Volume Weekly Surveillance	2
0BVSR 5.5.8.SX.5-2a	Group A Inservice Testing (IST) Requirements for Essential Service Water Makeup Pump 0B	2
0BVSR 5.5.8.SX.5-2b	Group B Inservice Testing (IST) Requirements for Essential Service Water Makeup Pump 0B	2
1BOSR 6.3.5-19	Unit One Main Steam Containment Isolation Valve Stoke Test	4
1BOSR 7.9.8-1	OA Essential Service Water Make-up Pump 18 Month Surveillance	2
1BOSR 7.9.8-2	OB Essential Service Water Make-up Pump 18 Month Surveillance	0
1BOSR SX-M1	1A AF Pump SX Suction Line Monthly Flushing Surveillance	4
2BOSR SX-M1	2A AF Pump SX Suction Line Monthly Flushing Surveillance	7
BAR 0-37-AB	SX CLG TWR Basin Level High Low	9

## PROCEDURES

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
BOP MS-6	Local Manual Operation of the Steam Generator Power Operated Relief Valves	7
BOP SX-12	Makeup to an Essential Service Water Mechanical Draft Cooling Tower Basin	9
BOP SX-10	Essential Service Water Make-up Pump Shutdown	11
MA-BY-725-515	Preventive Maintenance of Non-Segregated Bus Duct	6
OBOSR 5.5.8.SX.5-2c	Unit Zero Comprehensive Inservice Testing (IST) Requirements for Essential Service Water Makeup Pump 0B	0
MA-AA-725-102	Preventive Maintenance on Westinghouse Type DHP 4KV, 6.9KV, and 13.8KV Circuit Breakers	5
MA-AA-725-102	Preventive maintenance on Westinghouse type DHP 4KV, 6.9KV, and 13.8KV Circuit Breakers	5
MA-BY-773-402	Unit 2 – 4KV Safety Related Undervoltage and Degraded Voltage Relay Routine	3
1BEP-1	Loss of reactor or Secondary Coolant – Unit 1	107
1BOA ELEC-3	Loss of 4KV ESF Bus – Unit 1	103
1BOA ELEC-4	Loss of Offsite Power – Unit 1	107
2BOSR 8.1.11-2	Unit 2 – 2B Diesel Generator Sequencer Test 18 Months	9
2BCA-0.0	Loss of All AC Power Unit 2	106
2BOA ELEC-1	Loss of DC Bus Unit 2	102
2BOA ELEC-3	Loss of 4KV ESF Bus Unit 2	103
BAR-2-22-D6	125 VDC Bus 212 Ground	7
BAR-2-22-D7	DC Bus Tie Brkr to Bus 112 Close/Trip	1
BAR-2-22-D8	125VDC Batt Chgr 212 Trouble	3
BAR-2-22-E7	125VDC Batt Chgr 212 FD Brkr Trip	1
BOP DC-1	125V DC ESF Battery Chargers Start-Up	13
BOP DC-2	125V DC Battery Charger Shutdown	10
BOP DC-5	125V DC ESF Battery Equalization	16
BOP DC-6	125 VDC Control Power Transfer	2
BOP DC-6A1	DC Control Power Transfer from Normal to Reserve Source	52
BOP DC-6A2	DC Control Power Transfer from Reserve to Normal Source	52
BOP DC-7	125V DC ESF Bus Crosstie/Restoration	13
CC-AA-206	Fuse Control	5

**SURVEILLANCES (COMPLETED)**

<b><u>Number</u></b>	<b><u>Description or Title</u></b>	<b><u>Date or Revision</u></b>
1BOSR 0.5-2.RY.1	Unit 1 1RY8000A and 1RY8000B Stroke Test	03/23/09
2BOSR 0.5-2.RY.1	Unit 2 2RY8000A and 2RY8000B Stroke Test	01/18/09 03/23/09
2BOSR 0.5-2.RY.2	Unit 2 2RY455A and 2RY456 Stroke and Position Indication Test	10/23/08
2BVSR 5.c.3-2	Unit 2 Safety Injection System Hot Leg Flow Balance	10/19/08
2BVSR 5.c.3-1	Unit 2 Safety Injection System Cold Leg Flow Balance	10/19/08
2BVSR 5.5.8.SI.5-1a	Unit 2 Group A Inservice Testing (IST) Requirements for Safety Injection Pump 2SI01PA	01/27/09
2BVSR 5.5.8.SI.5-1c	Unit 2 Comprehensive Inservice Testing (IST) Requirements for Safety Injection Pump 2SI01PA	10/21/08
2BOSR 0.5-2.AF.1-2	Unit 2 Train B Auxiliary Feedwater Valves Stroke Time	01/05/09
2BOSR 4.11.3-1	Unit 2 Pressurizer PORV Accumulator Pressure Decay Test	10/18/08
MA-AP-773-541	Unit 2 – 4KV Bus 241 Cubicle Relay Routine	10/17/07
MA-AP-773-541	Unit 2 – 4KV Bus 241 Cubicle Relay Routine	10/09/06
MA-AP-773-542	Unit 2 – 4KV Bus 242 Cubicle Relay Routine	10/09/06
MA-BY-773-300	Byron Diesel Generators Relay Routine	12/04/07
MA-BY-773-502	Byron Unit 2 – 4KV UAT, SAT And Bus Tie Breakers Relay Routine – ACB 2422	04/26/05
MA-BY-773-502	Byron Unit 2 – 4KV UAT, SAT And Bus Tie Breakers Relay Routine – ACB 2421	10/09/06
MA-BY-773-502	Byron Unit 2 – 4KV UAT, SAT And Bus Tie Breakers Relay Routine – ACB 2424	04/18/07
MA-BY-OA-3-51000	Unit 2 – 4KV Bus 241 Cubicle Relay Routine	03/28/04
1/2BHSR DC-12	125 VDC Class 1E to Non-Class 1E Circuit Isolation Devices (Fuses)	2
2BOSR 8.6.1-2	Unit Two 125V DC ESF Battery Bank and Charger 212 Operability Weekly Surveillance	14
2BVSR 8.4.2-2	Unit 2 Bus 212 125V Battery Charger Operability	1
2BVSR 8.4.3-2	Unit 2 125 Volt Battery Bank 212 Service Test	1
2BVSR 8.6.6-2	Unit 2 Battery 212 125 Volt Battery Bank	2

**SURVEILLANCES (COMPLETED)**

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
MA-BY-721-060	5 Year Modified Performance Test 125 Volt Battery Bank 18 Month Surveillance	8
MA-BY-721-061	125 Volt Battery Bank Quarterly Surveillance	12
MA-BY-723-055	Nickel Cadmium Battery Bank Surveillance 18 Month Surveillance	6

**WORK DOCUMENTS**

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
WO 99226186	PORV Accumulator 1RY32MB Press Loop 1RY-021	07/27/07
WO 00856251	2RY8000A MOV Diagnostic Testing	04/19/07
WO 98054296	2AF013H MOV Diagnostic Testing	04/04/04
WO 00530934	2SX007 MOV Diagnostic Testing	04/26/04
WO 01019773	2RY455A AOV Diagnostic Testing	10/13/08
WO 00855440	Static "Baker" Testing on the 2A AF Pump Motor	03/28/06
WO 00935909	Replace Breaker Closing Relay 2AF01PA- 2ARAFPAX	07/10/08
WO 00856171	Change Grease in Coupling Per BMP 3229-1 Section F.2	10/19/06
WO 00950182	Repl Train A Low Suct. Pressure Interlock 2AF006/017- 2PSAF5	02/19/07
WO 00988211	(Sample) Motor Driven Aux Feedwater Pump 2A	06/20/08
WO 00972903	Preventive Maintenance on Breaker BUS 242, EM 4160 Volt Breaker Swap-out	07/21/07
WO 00750886	Preventive Maintenance on Breaker BUS 242, EM 4160 Volt Breaker Swap-out	03/20/05
WO 00512726	Preventive Maintenance on Breaker BUS 242, EM 4160 Volt Breaker Swap-out	02/24/03
WO 01024422 - 01	2B Diesel Generator SI Override Test	10/14/08
WO 01024425 - 01	2B Diesel Generator Sequencer Test	10/14/08
WO 01055330 - 03	2B Diesel generator 24 Hr. Endurance Run and Hot Restart	2/5/09
WO 01055330 - 01	2B Diesel generator 24 Hr. Endurance Run and Hot Restart	2/5/09
WO 00549115	Replace Capacitors All 7300uF 150 Vdc and 660 Vdc 1uF	08/01/05
WO 00664674	212 "B" Train 125V Battery Charger Operability Test	08/02/05
WO 00756561	Contingency General Troubleshooting Instructions (2DC04E)	08/02/05

**WORK DOCUMENTS**

<b><u>Number</u></b>	<b><u>Description or Title</u></b>	<b><u>Date or Revision</u></b>
WO 00856002	212 "B" Train 125V Battery Bank Service Test	04/15/07
WO 00999689	Contingency Troubleshooting Instructions (2DC04E)	10/03/07
WO 01023665	Clean, Inspect Conn on Bus/Panel & Perform Thermography	10/07/08
WO 01023666	Station Battery Surveillance 18 Mo Check Physical Condition, Clean	10/07/08
WO 01067206	212 "B" Train 125V Battery Bank 5 yr Capacity Test	10/07/08
WO 01194311	125V Battery Quarterly Surveillance	03/02/09
WO 01212645	125V DC ESF Battery Bank and Charger 212 Operability	02/26/09

## LIST OF ACRONYMS USED

AC	Alternating Current
ADAMS	Agencywide Document Access Management System
AFW	Auxiliary Feedwater
ALARA	As-Low-As-Is-Reasonably-Achievable
ASME	American Society of Mechanical Engineers
CAP	Corrective Action Program
CC	Component Cooling
CECo	Commonwealth Edison Company
CFR	Code of Federal Regulations
CR	Condition Report
CST	Condensate Storage Tank
DBD	Design Basis Document
DC	Direct Current
DRP	Division of Reactor Projects
EC	Engineering Change
EDG	Emergency Diesel Generator
EPRI	Electric Power Research Institute
ESW	Essential Service Water
FP	Fire Protection
FSAR	Final Safety Analysis Report
GDC	General Design Criteria
GL	Generic Letter
I&C	Instrumentation and Controls
IEEE	Institute of Electrical & Electronic Engineers
IMC	Inspection Manual Chapter
INPO	Institute of Nuclear Power Operations
IP	Inspection Procedure
IPE	Individual Plant Examination
IPEEE	Individual Plant Examination of External Events
IR	Inspection Report
IR	Issue Report
ISI	Inservice Inspection
kV	Kilovolt
LCO	Limiting Condition for Operation
LER	Licensee Event Report
LOCA	Loss of Coolant Accident
LOOP	Loss of Off-site Power
MCC	Motor Control Center
MCCB	Molded Case Circuit Breakers
MOV	Motor-Operated Valve
MRFF	Maintenance Rule Functional Failure
msec	Millisecond
MSIV	Main Steam Isolation Valve
NCV	Non-Cited Violation
NPSH	Net Positive Suction Head
NRC	U.S. Nuclear Regulatory Commission
PARS	Publicly Available Records
PI&R	Problem Identification and Resolution
PM	Planned or Preventative Maintenance

PMT	Post-Maintenance Testing
PORV	Power Operated Relief Valve
psid	Pounds Per Square Inch Differential
psig	Pounds Per Square Inch Gauge
RIS	Regulatory Issue Summaries
SBO	Station Blackout
SDP	Significance Determination Process
SER	Safety Evaluation Report
SG	Steam Generator
SGTR	Steam Generator Tube Rupture
SI	Safety Injection
SPAR	Standardized Plant Analysis Risk
SRA	Senior Reactor Analyst
SRV	Safety Relief Valve
SSC	Systems, Structures, and Components
SW	Service Water
TS	Technical Specification
UFSAR	Updated Final Safety Analysis Report
URI	Unresolved Item
Vac	Volts Alternating Current
Vdc	Volts Direct Current
WO	Work Order